Reserve Study Update Middle Village CDD Orange Park, Florida



Prepared for FY 2022 Report Date: May 10, 2022





May 10, 2022

Ms. Marilee Giles, District Manager Governmental Management Services 475 West Town Place, Suite 114 St. Augustine Florida 32092

Re: Reserve Study Report for Middle Village CDD

Dear Ms. Giles:

Community Advisors is pleased to provide this Reserve Study report for the above referenced District. A site visit was conducted to determine the condition of your major components and provide an opinion of their remaining useful life.

We have developed a plan to fund future capital component replacements which is dependent on adequate funding, component maintenance, usage, weather and other factors. Component replacement cost is determined using local vendors and industry standard publications. This Reserve Study was prepared under the guidelines of the National Reserve Study Standards which is administrated by CAI and the Standards of Practice establish by APRA. Once you have reviewed this report and considered recent expenditures and any historic cost data, we will make necessary adjustments

Respectively submitted,

Charles R. Sheppard *RS PRA CCI* Professional Reserve Analyst

10459 Hunters Creek Court Jacksonville, FL 32256 (904) 303-3275

www.communityadvisors.comm









SPECIAL NOTICE

THIS RESERVE ANALYLSIS INCLUDED A VISUAL OBSERVATION OF MAJOR COMPONENTS FOR YOUR PROPERTY. NO DISTRUCTION TESTING OR OTHER TESTING WAS CONDUCTED TO DETERMINE COMPONENT CONDITION. OUR ANALYSIS INCLUDES COMPONENTS WITH REPLACEMENT COST AND USEFUL LIFE PROJECTIONS THAT ARE TYPICAL FOR THIS TYPE OF FACILITY.

THIS ANALYSIS IS NOT A SAFETY INSPECTION OR STRUCTURAL INSPECTION AND WE RECOMMEND THE ASSOCIATION CONDUCT THOSE INSPECTIONS ON A REGULAR BASIS WITH OTHER CONSULTANTS.

TABLE OF CONTENTS

EXECUTIVE SUMMARY	
Executive Summary	1-1
Financial Summary - Recommended Funding Plan	1-2
Recommended Funding Plan Projection	1-3
Current Funding Plan vs Recommended Funding Plan	1-4
CURRENT FUNDING PLAN	
Financial Summary - Current Funding Plan	2-1
Current Funding Plan Projection	2-2
CASH FLOW	
Income & Expense Spreadsheet	3-1
EXPENDITURE DETAIL	
Annual Expenditure Detail	4-1
Asset Current Cost by Category	4-25
COMPONENT INVENTORY	
Component Inventory	5-1
Component Detail Index	5-8
Component Detail	5-15
DISCLOSURERS & INFORMATION	
Report Navigation	6-1
Methodology & Information	6-2
Terms of Service	6-3
Definitions	6-4

Executive Summary

Account Information

Account Name Middle Village CDD Account Number 1802

City Orange Park Last Site Visit April, 6 2022 State Florida Report Date May, 10 2022

In Service Date June, 1 2006 Report Version 1

Total Units 1 Fiscal Year Start October, 1 2022
Study Level Level II Update Fiscal year End September, 30 2023

Reserve Fund Information

Current Component Replacement Cost \$3,193,245 Number of Components 181

Reserve Fund Beginning Balance \$1,344,627
Billing Term Annually

Component Funding (Straight Line)

Recommended First Year Reserve Fund Contribution \$168,631
Interest Rate on Reserve Deposits 0%
Inflation Rate on Replacement Cost 0%

Pooled Cash (Current Funding Plan)

Current Year Reserve Fund Contribution \$19,556
Interest Rate on Reserve Deposits Variable
Inflation Rate on Replacement Cost Variable
Annual Contribution Increases 1.0%

Pooled Cash (Recommended Funding Plan)

Recommended First Year Reserve Fund Contribution
Interest Rate on Reserve Deposits
Variable
Inflation Rate on Replacement Cost
Annual Contribution Increases

\$263,917
Variable
Variable
1.0%


Comments

- Current funding level is not adequate for future component replacement.
- Recommended funding plan requires larger contributions for adequate funding.


Middle Village CDD Financial Summary - Recommended Funding Plan

Begining Balance: \$1,344,627 Fully Funded: \$1,928,005 Tax Rate:0%

	U	\mathcal{C}	. , ,		•	, , ,				
	A SON ON		A CO	ida			digital digita	ę.	28 (A) 29 28 (A) 29	, so ~ 1
	Nacety	, ida	Author Stories	in st stil			.ecologiju	A Segular Segu	20 Call 25	Fig. 18
Year	€8,0°	Tallaga de	AND CONTRACTOR IN	Otoet cons	A Signal Signal	4 - Tries	dig the sing	र्ड की विष्ट	र्रहकूरिक्या, रह	in Ainth
22-23	3,193,245	6.0%	263,917	0	3.50%		400,775	1,207,770	1,807,128	67%
23-24	3,384,839	5.0%	266,557	0	0.50%	208	88,044	1,386,491	2,002,377	69%
24-25	3,554,081	4.0%	269,222	0	1.00%	2,806	30,483	1,628,036	2,255,886	72%
25-26	3,696,244	3.0%	271,914	0	1.50%	3,497	322,211	1,581,237	2,205,463	72%
26-27	3,807,132	3.0%	274,634	0	2.00%	9,264	48,047	1,817,087	2,442,329	74%
27-28	3,921,346	3.0%	277,380	0	2.50%	7,399	453,899	1,647,966	2,276,243	72%
28-29	4,038,986	3.0%	280,154	0	3.00%	8,740	292,156	1,644,704	2,278,865	72%
29-30	4,160,156	3.0%	282,955	0	3.50%	16,249	118,776	1,825,132	2,467,204	74%
30-31	4,284,960	3.0%	285,785	0	3.50%	9,547	493,520	1,626,944	2,283,206	71%
31-32	4,413,509	3.0%	288,643	0	3.50%	16,931	87,213	1,845,304	2,519,695	73%
32-33	4,545,914	3.0%	291,529	0	3.50%	22,708	143,395	2,016,147	2,713,146	74%
33-34	4,682,292	3.0%	294,444	0	3.50%	31,316	71,233	2,270,673	2,994,693	76%
34-35	4,822,761	3.0%	297,389	0	3.50%	34,172	247,091	2,355,143	3,111,759	76%
35-36	4,967,443	3.0%	300,363	0	3.50%	2,540	1,238,305	1,419,740	2,219,839	64%
36-37	5,116,467	3.0%	303,366	0	3.50%	11,363	53,821	1,680,649	2,529,885	66%
37-38	5,269,961	3.0%	306,400	0	3.50%	9,424	373,160	1,623,313	2,529,280	64%
38-39	5,428,060	3.0%	309,464	0	3.50%	14,996	159,691	1,788,082	2,757,765	65%
39-40	5,590,901	3.0%	312,559	0	3.50%	24,898	44,647	2,080,891	3,121,113	67%
40-41	5,758,628	3.0%	315,684	0	3.50%	19,622	491,323	1,924,874	3,045,083	63%
41-42	5,931,387	3.0%	318,841	0	3.50%	24,698	193,438	2,074,975	3,283,686	63%
42-43	6,109,329	3.0%	322,029	0	3.50%	23,833	371,442	2,049,395	3,356,497	61%
43-44	6,292,609	3.0%	325,250	0	3.50%	17,670	525,165	1,867,149	3,283,864	57%
44-45	6,481,387	3.0%	328,502	0	3.50%	27,633	61,500	2,161,784	3,697,655	58%
45-46	6,675,828	3.0%	331,787	0	3.50%	14,717	728,458	1,779,830	3,448,252	52%
46-47	6,876,103	3.0%	335,105	0	3.50%		914,387	1,200,548	3,011,559	40%
47-48	7,082,386	3.0%	338,456	0	3.50%		700,888	838,116	2,793,719	30%
48-49	7,294,858	3.0%	341,841	0	3.50%		159,428	1,020,529	3,139,460	33%
49-50	7,513,704	3.0%	345,259	0	3.50%		189,911	1,175,877	3,476,961	34%
50-51	7,739,115	3.0%	348,712	0	3.50%		259,833	1,264,756	3,765,735	34%
51-52	7,971,288	3.0%	352,199	0	3.50%	6,954	73,641	1,550,268	4,268,512	36%



This chart illustrates how the recommended funding plan performes over time.




This chart illustrates annual expenditures and compares the current funding plan to the recommended funding plan.

Middle Village CDD Financial Summary - Current Funding Plan

Begining Balance: \$1,344,627 Fully Funded: \$1,928,005 Tax Rate:0%

	0	U	, , ,		•	. , ,				
	officit	S	~ .º .v	idot .	n &	~	, d (i)	je Go s	رق رقاق	
Year	A SHOW SE SHOW	tilda sas	AND SON	Oziet rody	The Sale	* The state of the	rio di di	Top Sylphon	764 1917 71 164 164	के अविवर्ष
22-23	3,193,245	6.0%	19,556	0	3.50%		400,775	963,408	1,807,128	53%
23-24	3,384,839	5.0%	19,752	0	0.50%		88,044	895,116	2,002,377	45%
24-25	3,554,081	4.0%	19,732	0	1.00%		30,483	884,582	2,255,886	39%
25-26	3,696,244	3.0%	20,149	0	1.50%		322,211	582,520	2,205,463	26%
26-27	3,807,132	3.0%	20,350	0	2.00%		48,047	554,823	2,442,329	23%
27-28	3,921,346	3.0%	20,554	0	2.50%		453,899	121,478	2,276,243	5%
28-29	4,038,986	3.0%	20,759	0	3.00%		292,156	-149,919	2,278,865	370
29-30	4,160,156	3.0%	20,967	0	3.50%		118,776	-247,729	2,467,204	
30-31	4,284,960	3.0%	21,176	0	3.50%		493,520	-720,073	2,283,206	
31-32	4,413,509	3.0%	21,388	0	3.50%		87,213	-785,897	2,519,695	
32-33	4,545,914	3.0%	21,602	0	3.50%		143,395	-907,691	2,713,146	
33-34	4,682,292	3.0%	21,818	0	3.50%		71,233	-957,106	2,994,693	
34-35	4,822,761	3.0%	22,036	0	3.50%		247,091	-1,182,161	3,111,759	
35-36	4,967,443	3.0%	22,257	0	3.50%		1,238,305	-2,398,210	2,219,839	
36-37	5,116,467	3.0%	22,479	0	3.50%		53,821	-2,429,551	2,529,885	
37-38	5,269,961	3.0%	22,704	0	3.50%		373,160	-2,780,007	2,529,280	
38-39	5,428,060	3.0%	22,931	0	3.50%		159,691	-2,916,767	2,757,765	
39-40	5,590,901	3.0%	23,160	0	3.50%		44,647	-2,938,254	3,121,113	
40-41	5,758,628	3.0%	23,392	0	3.50%		491,323	-3,406,185	3,045,083	
41-42	5,931,387	3.0%	23,626	0	3.50%		193,438	-3,575,997	3,283,686	
42-43	6,109,329	3.0%	23,862	0	3.50%		371,442	-3,923,578	3,356,497	
43-44	6,292,609	3.0%	24,101	0	3.50%		525,165	-4,424,642	3,283,864	
44-45	6,481,387	3.0%	24,342	0	3.50%		61,500	-4,461,801	3,697,655	
45-46	6,675,828	3.0%	24,585	0	3.50%		728,458	-5,165,674	3,448,252	
46-47	6,876,103	3.0%	24,831	0	3.50%		914,387	-6,055,230	3,011,559	
47-48	7,082,386	3.0%	25,079	0	3.50%		700,888	-6,731,039	2,793,719	
48-49	7,294,858	3.0%	25,330	0	3.50%		159,428	-6,865,138	3,139,460	
49-50	7,513,704	3.0%	25,583	0	3.50%		189,911	-7,029,465	3,476,961	
50-51	7,739,115	3.0%	25,839	0	3.50%		259,833	-7,263,459	3,765,735	
51-52	7,971,288	3.0%	26,098	0	3.50%		73,641	-7,311,002	4,268,512	



This chart illustrates how the CDD's current funding plan will perform over time.

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Beginning Balance	1,344,627	1,207,770	1,386,491	1,628,036	1,581,237	1,817,087	1,647,966	1,644,704	1,825,132	1,626,944
Annual Assessment	263,917	266,557	269,222	271,914	274,634	277,380	280,154	282,955	285,785	288,643
Interest Earned		208	2,806	3,497	9,264	7,399	8,740	16,249	9,547	16,931
Expenditures	400,775	88,044	30,483	322,211	48,047	453,899	292,156	118,776	493,520	87,213
Fully Funded Reserves	1,807,128	2,002,377	2,255,886	2,205,463	2,442,329	2,276,243	2,278,865	2,467,204	2,283,206	2,519,695
Percent Fully Funded	67%	69%	72%	72%	74%	72%	72%	74%	71%	73%
Ending Balance	1,207,770	1,386,491	1,628,036	1,581,237	1,817,087	1,647,966	1,644,704	1,825,132	1,626,944	1,845,304
Description										
Site Components - General										
Decorative Fountain Refurbishment Allowance	3,000									
Irrigation System Repair Allowance	3,000					3,684				
Well 4" Pump - Tennis Courts	4,500									
Well 6" Pump - Oakleaf Plantation Parkway	6,200									
Well 6" Pump - Plantation Oaks Blvd. West	6,200									
Wood Boardwalk Replacement										
Site Components - General Total:	22,900					3,684				
Site Components - Monuments										
Brick Tuck Point & Seal - Bell Tower				21,530						
Brick Tuck Point & Seal - Clock Tower				24,401						
Exterior Paint - Bell Tower	6,000									
Exterior Paint - Clock Tower	6,000									
Metal Roof - Bell Tower										
Metal Roof - Clock Tower	10.00			47.000						
Site Components - Monuments Total:	12,000			45,930						
Site Components - Signage										
Refurbishment Allowance - Amenity Monument Si								3,908		
Refurbishment Allowance - Deerview Lane entry								3,908		
Refurbishment Allowance - Hamilton Glen Entry								3,908		
Refurbishment Allowance - Whitfield Entry								3,908		
Site Components - Signage Total:								15,634		

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description										
Site Components - Fencing										
Aluminum Fence 8 Ft - Amenity										
Chain Link Fence - Maintence Shed										
Dumpster Enclosure Gates	6,400									
Vinyl Fencing - Deerview										
Vinyl Fencing - Hamilton Glen										
Vinyl Fencing - Whitfield										
Site Components - Fencing Total:	6,400									
Site Components - Parking Lots										
Concrete Pavers - Parking Lot										
Light Poles									15,029	
Light Poles									33,815	
Parking Lot Mill & Resurface						267,192				
Site Components - Parking Lots Total:						267,192			48,845	
Clubhouse - General										
Access Control Panel							4,806			
Exterior Painting - Clubhouse				47,449						
Guard Rail									30,783	
Kitchen Cabinet & Equipment - Snack Bar				9,723						
Monument Stair Railings										
Painting - Guard Rails	3,162									
Painting - Monument Stair Rails	4,055									
Security Camera System Allowance	15,000								0.454	
Water Coolers	2.060								8,454	
Water Heater Clubhouse - General Total:	3,060			57 170			1 00.6		20.227	
Ciudnouse - General Iotal:	25,277			57,172			4,806		39,237	
Clubhouse - Roofing										
Asphalt Shingles		64,830								
Standing Seam Metal Roof										
Clubhouse - Roofing Total:		64,830								

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description										
Clubhouse - Fitness Center										
Carpet Tile	6,270									
Fitness Equip Partial Allowance	3,000	3,180	3,339	3,473	3,577	3,684	3,795	3,908	4,026	4,146
Interior Painting - Fitness	2,304								3,092	
Wall Mounted Televisions		2,544				2 (0.1		• • • • •		
Clubhouse - Fitness Center Total:	11,574	5,724	3,339	3,473	3,577	3,684	3,795	3,908	7,117	4,146
Clubhouse - Locker Rooms										
Refurbishment Allowance - Locker Rooms				77,785						
Clubhouse - Locker Rooms Total:				77,785						
Clubhouse - Second Floor Components										
Cabinets & Laminate Top - Kitchen									4,468	
Floor Tile - Kitchen									3,757	
Folding Tables & Chairs Allowance	3,000									
Freezer										
Ice Machine	6.020			3,704		0.510				
Interior Wall Painting	6,930			605		8,510				
Microwave - Kitchen Range - Kitchen				695 1,852						
Refrigerator - Kitchen				1,652						
Refurbishment Allowance - Restooms							37,237			
Vinyl Flooring										
Window Treatment Allowance				7,408						
Clubhouse - Second Floor Components Total:	9,930			13,659		8,510	37,237		8,226	
Clubhouse - Mechanical Systems										
HVAC Unit 1										11,057
HVAC Unit 2										26,537
HVAC Unit 3										,
Clubhouse - Mechanical Systems Total:										37,594

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description										
Clubhouse - Elevator Elevator Cab Refurbishment Elevator Equipment Modernization Clubhouse - Elevator Total:									11,540	
									11,540	
Lake Pavilion Composit Deck & Rails Exterior Painting - Pavilion	2,400									
Metal Roof - Pavilion Wood Bulkhead	2,100									
Wood Repair - Pavilion Lake Pavilion Total:	2,400								20,853 20,853	
	2,400								20,033	
Lawn Pavilions Asphalt Shingles Exterior Painting				6,112	5,723					
Lawn Pavilions Total:				6,112	5,723					
Sports Pavilion										
Exterior Painting Metal Roof	3,600									
Restroom Refurbishment Water Cooler	2,200			8,103						
Sports Pavilion Total:	5,800			8,103						
Ball Fields										
Chain Link Back Stops						22,104				
Chain Link Dugouts & Roof Chain Link Fencing 4 Ft						15,719 17,794				
Chain Link Fencing 4 Ft Chain Link Fencing 6 Ft						17,794				
Ball Fields Total:						65,834				
Basketball Courts										
Basketball Court Resurfacing Basketball Pole & Backboard	8,400 7,200					10,315				

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description										
Basketball Courts continued										
Chain Link Fencing			15,457							
Light Poles									16,639	
Basketball Courts Total:	15,600		15,457			10,315			16,639	
Tennis Complex										
Asphalt Shingles - Maintenance Building				7,130						
Exterior Painting - Maintenance Building	2,200									
Exterior Painting - Pavilion	5,600					6,877				
HVAC Unit - Tennis Office	4,800									
Metal Roof - Pavilion										
Refurbishment Allowance - Restrooms				23,150						
Water Coolers										
Wood Pergola - Pavilion						13,754				
Tennis Complex Total:	12,600			30,281		20,631				
Tennis Courts										
Aluminium Fence - Patio										
Aluminum Bleachers										
Chain Link Fencing - 10 Ft										
Chain Link Fencing - 4 Ft								7,387		
Light Poles									94,469	
Shade Pavilions				9,260						
Tennis Court Replenishment Allowance	17,600				20,984				23,617	
Wind Screens							11,131			
Wood Bulkheads										
Tennis Courts Total:	17,600			9,260	20,984		11,131	7,387	118,086	
Swimming Pools - General										
Aluminium Fencing										
Asphalt Shingles - Sidewalk Pavilion				2,037						
Concrete Pavers - Pool Decks										
Exterior Painting - Pool Slide Tower							15,178			
HVAC Unit - Pool Office	3,200									

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description										
Swimming Pools - General continued										
Lifeguard Chairs Light Poles	4,200								14,492	
Metal Roof - Pool Slide Building		•		• 004	• 004	• • •				
Pool Furniture Annual Allowance	2,500	2,650	2,782	2,894	2,981	3,070	3,162	3,257	3,355	3,455
Pool Pumps & Equipment Annual Allowance Pool Shade Structures	8,000	8,480	8,904	9,260	9,538	9,824	10,119	10,422	10,735	11,057
Pool Slide Railing									17,176	
Pool Slide Refurbishment										22,114
Vinyl Fence - Pool Equipment Yard	1= 000	11.100	44.60.6	11101	10.710	10001	40.450	10.70	4===0	
Swimming Pools - General Total:	17,900	11,130	11,686	14,191	12,519	12,894	28,459	13,679	45,758	36,627
Family Pool Complex										
Exterior Painting - Pavilion	6,800									
Metal Roof - Pavilion										
Pool Resurfacing							159,372			
Refurbishment Allowance - Restrooms				13,890					c0 11 c	
Wood Pergola				10.000			150 050		60,116	
Family Pool Complex Total:	6,800			13,890			159,372		60,116	
Lap Pool Complex										
Exterior Painting - Pavilion					3,815					
Exterior Painting - Restroom Pavilion	2,250									
Lane Divider Reel									2,603	
Lane Dividers	4,160									
Light Poles										
Metal Roof - Pavilion										
Metal Roof - Restroom Pavilion						5 0.040				
Pool Heater Allowance		2.202				50,840				
Pool Decomposition	96.044	3,392								
Pool Resurfacing	86,044 5,040								6762	
Pool Solar Blanket Pool Solar Blanket Reel	5,040				1,431				6,763	
				18,520	1,431					
Refurbishment Allowance - Lap Pool Restrooms				18,320						

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description										
Lap Pool Complex continued										
Starting Platforms									21,739	
Water Coolers	2,200									
Lap Pool Complex Total:	99,694	3,392		18,520	5,246	50,840			31,105	
Splash Pool										
Pool Play Equipment Allowance									53,675	
Pool Resurfacing							28,383			
Splash Pool Total:							28,383		53,675	
Playground - Clubhouse										
Bipod Swings - 2 Bay										4,423
Cresent Climber										
Park Benches									17,444	
Picnic Tables						10,315				
Plastic Play Surface Border								#0 63 6		
Play Equipment Allowance							6.224	58,626		
Speedy Spinner Spring Riders							6,324			4,423
Wood Park Benches										4,423
Wood Play Equipment								19,542		
Playground - Clubhouse Total:						10,315	6,324	78,168	17,444	8,846
Dlayamayand Dagwigayy Dawly										
Playground - Deerview Park Bi-Pod Swing Set	3,200									
Cresent Climber	3,200	2,968								
Gazebo Roof		2,700								
Park Benches	1,200									
Picnic Tables	2,600									
Plastic Play Surface Border				7,074						
Play Equipment Allowance	30,000									
Spring Rider	1,600									
Vinyl Privacy Fence									14.070	
Vinyl Ranch Fence	20 (00	2.069		7.074					14,879	
Playground - Deerview Park Total:	38,600	2,968		7,074					14,879	

Community Advisors Page 3-7 May 10, 2022

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description										
Playground - Hamilton Glen Park										
Bi-Pod Swing Set	3,200									
Gazebo Roof										
Park Bench	1,300									
Picnic Tables	2,600									
Plastic Play Surface Border				2,917						
Play Equipment Allowance	30,000									
Vinyl Privacy Fence										
Playground - Hamilton Glen Park Total:	37,100			2,917						
Playgrounds - Whitfield Park										
Bi-Pod Swing Set	3,200									
Gazebo Roof										
Park Bench	1,200									
Picnic Tables	2,600									
Plastic Play Surface Border				6,320						
Play Equipment Allowance	30,000									
Vinyl Privacy Fence										
Vinyl Ranch Fence										
Playgrounds - Whitfield Park Total:	37,000			6,320						
Maintenance Shop & Equipment										
All Terain Vehicle							12,649			
Exterior Painting	6,600									
Golf Cart	15,000									
Jon Boat & Motor Allowance				7,524						
Metal Roof										
Maintenance Shop & Equipment Total:	21,600			7,524			12,649			
Operating Expense										
Flooring - Office	Unfunded									
Furniture - Second Floor Clubhouse	Unfunded									
Interior Painting - Office	Unfunded									
Office Equipment & Furniture Allowance	Unfunded									

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description										
Operating Expense continued										
Parking Lot Seal Coat	Unfunded									
Steel Trash Cans	Unfunded									
Wood Mulch - Play Areas	Unfunded									
Components Not Included										
Clock Tower Clock	Unfunded									
Fabric Shade Awnings - Tennis Curts	Unfunded									
Year Total:	400,775	88,044	30,483	322,211	48,047	453,899	292,156	118,776	493,520	87,213

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Beginning Balance	1,845,304	2,016,147	2,270,673	2,355,143	1,419,740	1,680,649	1,623,313	1,788,082	2,080,891	1,924,874
Annual Assessment	291,529	294,444	297,389	300,363	303,366	306,400	309,464	312,559	315,684	318,841
Interest Earned	22,708	31,316	34,172	2,540	11,363	9,424	14,996	24,898	19,622	24,698
Expenditures	143,395	71,233	247,091	1,238,305	53,821	373,160	159,691	44,647	491,323	193,438
Fully Funded Reserves	2,713,146	2,994,693	3,111,759	2,219,839	2,529,885	2,529,280	2,757,765	3,121,113	3,045,083	3,283,686
Percent Fully Funded	74%	76%	76%	64%	66%	64%	65%	67%	63%	63%
Ending Balance	2,016,147	2,270,673	2,355,143	1,419,740	1,680,649	1,623,313	1,788,082	2,080,891	1,924,874	2,074,975
D 1.1										
Description Site Commonweater Consumate										
Site Components - General	4 271									
Decorative Fountain Refurbishment Allowance	4,271					4.051				
Irrigation System Repair Allowance	4,271		6.706			4,951				
Well 4" Pump - Tennis Courts			6,796							
Well 6" Pump - Oakleaf Plantation Parkway			9,364							
Well 6" Pump - Plantation Oaks Blvd. West			9,364							
Wood Boardwalk Replacement Site Components - General Total:	0.543		25 524			4.051				
Site Components - General Total:	8,542		25,524			4,951				
Site Components - Monuments										
Brick Tuck Point & Seal - Bell Tower										
Brick Tuck Point & Seal - Clock Tower										
Exterior Paint - Bell Tower			9,062							
Exterior Paint - Clock Tower			9,062							
Metal Roof - Bell Tower									14,699	
Metal Roof - Clock Tower									14,699	
Site Components - Monuments Total:			18,124						29,399	
Site Components - Signage										
Refurbishment Allowance - Amenity Monument Si	i							5,253		
Refurbishment Allowance - Deerview Lane entry								5,253		
Refurbishment Allowance - Hamilton Glen Entry								5,253		
Refurbishment Allowance - Whitfield Entry								5,253		
Site Components - Signage Total:								21,010		

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Description	02 00	00 01	0.00		0001	07 00	000)	07 10	10 11	11 12
Site Components - Fencing										
Aluminum Fence 8 Ft - Amenity										
Chain Link Fence - Maintence Shed										
Dumpster Enclosure Gates										
Vinyl Fencing - Deerview				356,857						
Vinyl Fencing - Hamilton Glen				116,991						
Vinyl Fencing - Whitfield				183,251						
Site Components - Fencing Total:				657,099						
Site Components - Parking Lots										
Concrete Pavers - Parking Lot				10,143						
Light Poles										
Light Poles										
Parking Lot Mill & Resurface										
Site Components - Parking Lots Total:				10,143						
Clubhouse - General										
Access Control Panel										
Exterior Painting - Clubhouse				63,768						
Guard Rail										
Kitchen Cabinet & Equipment - Snack Bar										
Monument Stair Railings	. =0.4								64,474	
Painting - Guard Rails	4,501									
Painting - Monument Stair Rails	5,772									
Security Camera System Allowance Water Coolers	21,354									
Water Coolers Water Heater			4,622							
Clubhouse - General Total:	31,628		4,622	63,768					64,474	
	31,020		7,022	03,700					UT,T/T	
Clubhouse - Roofing										
Asphalt Shingles										
Standing Seam Metal Roof									89,448	
Clubhouse - Roofing Total:									89,448	

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Description										
Clubhouse - Fitness Center										
Carpet Tile	8,926									
Fitness Equip Partial Allowance	4,271	4,399	4,531	4,667	4,807	4,951	5,100	5,253	5,410	5,572
Interior Painting - Fitness							3,916			
Wall Mounted Televisions		3,519								
Clubhouse - Fitness Center Total:	13,197	7,918	4,531	4,667	4,807	4,951	9,016	5,253	5,410	5,572
Clubhouse - Locker Rooms										
Refurbishment Allowance - Locker Rooms										
Clubhouse - Locker Rooms Total:										
Clubhouse - Second Floor Components										
Cabinets & Laminate Top - Kitchen										
Floor Tile - Kitchen										
Folding Tables & Chairs Allowance						4,951				
Freezer	5,410									
Ice Machine	0.966					11 427				
Interior Wall Painting Microwave - Kitchen	9,866			933		11,437				
Range - Kitchen				933		2,641				
Refrigerator - Kitchen				5,445		2,071				
Refurbishment Allowance - Restooms				0,						
Vinyl Flooring						24,887				
Window Treatment Allowance										
Clubhouse - Second Floor Components Total:	15,275			6,378		43,916				
Clubhouse - Mechanical Systems										
HVAC Unit 1										
HVAC Unit 2										
HVAC Unit 3		28,153								
Clubhouse - Mechanical Systems Total:		28,153								

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Description Clubhouse - Elevator										
Elevator Cab Refurbishment Elevator Equipment Modernization Clubhouse - Elevator Total:									56,265 56,265	
Lake Pavilion Composit Deck & Rails									ŕ	21,993
Exterior Painting - Pavilion Metal Roof - Pavilion Wood Bulkhead	3,417	15,953							18,467	
Wood Repair - Pavilion		15.050							28,025	24.002
Lake Pavilion Total:	3,417	15,953							46,491	21,993
Lawn Pavilions Asphalt Shingles Exterior Painting Lawn Pavilions Total:					7,691 7,691					
					7,071					
Sports Pavilion Exterior Painting Metal Roof	5,125								25,103	
Restroom Refurbishment Water Cooler			3,323							
Sports Pavilion Total:	5,125		3,323						25,103	
Ball Fields Chain Link Back Stops Chain Link Dugouts & Roof										
Chain Link Fencing 4 Ft Chain Link Fencing 6 Ft Ball Fields Total:										
Basketball Courts										
Basketball Court Resurfacing Basketball Pole & Backboard	11,958					13,863 11,882				

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Description										
Basketball Courts continued										
Chain Link Fencing										
Light Poles										
Basketball Courts Total:	11,958					25,745				
Tennis Complex										
Asphalt Shingles - Maintenance Building										
Exterior Painting - Maintenance Building	3,132									
Exterior Painting - Pavilion	7,972					9,242				
HVAC Unit - Tennis Office			7,249							
Metal Roof - Pavilion									58,603	
Refurbishment Allowance - Restrooms										
Water Coolers				6,534						
Wood Pergola - Pavilion										
Tennis Complex Total:	11,104		7,249	6,534		9,242			58,603	
Tennis Courts										
Aluminium Fence - Patio										
Aluminum Bleachers		3,812								
Chain Link Fencing - 10 Ft										
Chain Link Fencing - 4 Ft										
Light Poles										
Shade Pavilions										
Tennis Court Replenishment Allowance			26,581				29,917			
Wind Screens							14,959			
Wood Bulkheads				37,521						
Tennis Courts Total:		3,812	26,581	37,521			44,876			
Swimming Pools - General										
Aluminium Fencing				47,378						
Asphalt Shingles - Sidewalk Pavilion										
Concrete Pavers - Pool Decks				168,644						
Exterior Painting - Pool Slide Tower							20,398			
HVAC Unit - Pool Office			4,833							

Community Advisors Page 3-14 May 10, 2022

	22.22	22.24	24.25	25.26	26.25	25 20	20.20	20.40	40 41	41 40
Description	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
-										
Swimming Pools - General continued						5.021				
Lifeguard Chairs						6,931				
Light Poles				22 401						
Metal Roof - Pool Slide Building	2.550	2.666	2.77.6	22,401	4.006	1.106	4.250	4.077	4.500	4 < 4.4
Pool Furniture Annual Allowance	3,559	3,666	3,776	3,889	4,006	4,126	4,250	4,377	4,508	4,644
Pool Pumps & Equipment Annual Allowance	11,389	11,730	12,082	12,445	12,818	13,203	13,599	14,007	14,427	14,860
Pool Shade Structures							33,997			
Pool Slide Railing										20.720
Pool Slide Refurbishment				6.044						29,720
Vinyl Fence - Pool Equipment Yard	14.040	15.206	20.601	6,944	16004	24.260	5 2.244	10.204	10.025	40.000
Swimming Pools - General Total:	14,948	15,396	20,691	261,701	16,824	24,260	72,244	18,384	18,935	49,223
Family Pool Complex										
Exterior Painting - Pavilion	9,681									
Metal Roof - Pavilion	•			79,996						
Pool Resurfacing										
Refurbishment Allowance - Restrooms										
Wood Pergola										
Family Pool Complex Total:	9,681			79,996						
Lap Pool Complex										
Exterior Painting - Pavilion					5,127					
Exterior Painting - Restroom Pavilion	3,203				3,127					
Lane Divider Reel	3,203									
Lane Dividers	5,922									
Light Poles	3,722			28,001						
Metal Roof - Pavilion				20,001						
Metal Roof - Restroom Pavilion										
Pool Heater Allowance						68,324				
Pool Lift						,	5,440			
Pool Resurfacing			129,952				- ,			
Pool Solar Blanket			. ,				8,567			
Pool Solar Blanket Reel							- ,			
Refurbishment Allowance - Lap Pool Restrooms										

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Description										
Lap Pool Complex continued										
Starting Platforms										
Water Coolers			3,323	20.004		60.204	4400=			
Lap Pool Complex Total:	9,125		133,275	28,001	5,127	68,324	14,007			
Splash Pool										
Pool Play Equipment Allowance										
Pool Resurfacing										
Splash Pool Total:										
Playground - Clubhouse										
Bipod Swings - 2 Bay										
Cresent Climber			3,172							
Park Benches										
Picnic Tables					16 407					
Plastic Play Surface Border Play Equipment Allowance					16,487					83,587
Speedy Spinner									9,017	65,567
Spring Riders									,,017	
Wood Park Benches					2,884					
Wood Play Equipment										27,862
Playground - Clubhouse Total:			3,172		19,372				9,017	111,449
Playground - Deerview Park										
Bi-Pod Swing Set						5,281				
Cresent Climber										5,201
Gazebo Roof				7,467						
Park Benches							2,040			
Picnic Tables Plactic Play Symfons Bondon							4,420			
Plastic Play Surface Border Play Equipment Allowance						49,510				
Spring Rider						2,641				
Vinyl Privacy Fence				9,645		- ,0.1				
Vinyl Ranch Fence										
Playground - Deerview Park Total:				17,112		57,432	6,459			5,201

Community Advisors Page 3-16 May 10, 2022

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Description										
Playground - Hamilton Glen Park										
Bi-Pod Swing Set						5,281				
Gazebo Roof				7,467						
Park Bench							2,210			
Picnic Tables							4,420			
Plastic Play Surface Border										
Play Equipment Allowance						49,510				
Vinyl Privacy Fence				11,429						
Playground - Hamilton Glen Park Total:				18,896		54,792	6,629			
Playgrounds - Whitfield Park										
Bi-Pod Swing Set						5,281				
Gazebo Roof				7,467						
Park Bench							2,040			
Picnic Tables							4,420			
Plastic Play Surface Border										
Play Equipment Allowance						49,510				
Vinyl Privacy Fence				20,543						
Vinyl Ranch Fence				18,481						
Playgrounds - Whitfield Park Total:				46,491		54,792	6,459			
Maintenance Shop & Equipment										
All Terain Vehicle										
Exterior Painting	9,396									
Golf Cart						24,755				
Jon Boat & Motor Allowance										
Metal Roof									88,178	
Maintenance Shop & Equipment Total:	9,396					24,755			88,178	
Operating Expense										
Flooring - Office	Unfunded									
Furniture - Second Floor Clubhouse	Unfunded									
Interior Painting - Office	Unfunded									
Office Equipment & Furniture Allowance	Unfunded									

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Description										
Operating Expense continued										
Parking Lot Seal Coat	Unfunded									
Steel Trash Cans	Unfunded									
Wood Mulch - Play Areas	Unfunded									
Components Not Included										
Clock Tower Clock	Unfunded									
Fabric Shade Awnings - Tennis Curts	Unfunded									
Year Total:	143,395	71,233	247,091	1,238,305	53,821	373,160	159,691	44,647	491,323	193,438

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Beginning Balance Annual Assessment	2,074,975 322,029	325,250	1,867,149 328,502	2,161,784 331,787	1,779,830 335,105	1,200,548 338,456	838,116 341,841	1,020,529 345,259	1,175,877 348,712	1,264,756 352,199
Interest Earned Expenditures	23,833 371,442	17,670 525,165	27,633 61,500	14,717 728,458	914,387	700,888	159,428	189,911	259,833	6,954 73,641
Fully Funded Reserves	3,356,497	3,283,864		3,448,252	3,011,559		3,139,460	,	3,765,735	4,268,512
Percent Fully Funded	61%	57%	58%	52%	40%	30%	33%	34%	34%	36%
Ending Balance	2,049,395	1,867,149	2,161,784	1,779,830	1,200,548	838,116	1,020,529	1,175,877	1,264,756	1,550,268
Description										
Site Components - General										
Decorative Fountain Refurbishment Allowance	5,740									
Irrigation System Repair Allowance	5,740					6,654				
Well 4" Pump - Tennis Courts					9,690					
Well 6" Pump - Oakleaf Plantation Parkway					13,351					
Well 6" Pump - Plantation Oaks Blvd. West					13,351					
Wood Boardwalk Replacement					307,149					
Site Components - General Total:	11,479				343,540	6,654				
Site Components - Monuments										
Brick Tuck Point & Seal - Bell Tower				38,885						
Brick Tuck Point & Seal - Clock Tower				44,070						
Exterior Paint - Bell Tower					12,920					
Exterior Paint - Clock Tower					12,920					
Metal Roof - Bell Tower										
Metal Roof - Clock Tower										
Site Components - Monuments Total:				82,955	25,840					
Site Components - Signage										
Refurbishment Allowance - Amenity Monument S	i							7,059		
Refurbishment Allowance - Deerview Lane entry								7,059		
Refurbishment Allowance - Hamilton Glen Entry								7,059		
Refurbishment Allowance - Whitfield Entry								7,059		
Site Components - Signage Total:		<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	28,236		

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description										
Site Components - Fencing										
Aluminum Fence 8 Ft - Amenity					182,740					
Chain Link Fence - Maintence Shed	16,607									
Dumpster Enclosure Gates	12,245									
Vinyl Fencing - Deerview										
Vinyl Fencing - Hamilton Glen										
Vinyl Fencing - Whitfield										
Site Components - Fencing Total:	28,851				182,740					
Site Components - Parking Lots										
Concrete Pavers - Parking Lot										
Light Poles										
Light Poles										
Parking Lot Mill & Resurface						482,578				
Site Components - Parking Lots Total:						482,578				
Clubhouse - General										
Access Control Panel		7,488								
Exterior Painting - Clubhouse				85,698						
Guard Rail										
Kitchen Cabinet & Equipment - Snack Bar				17,561						
Monument Stair Railings										
Painting - Guard Rails	6,050									
Painting - Monument Stair Rails	7,758									
Security Camera System Allowance	28,698									
Water Coolers	12,053				<i>(5</i> 00					
Water Heater	E4 550	7 400		102.250	6,589					
Clubhouse - General Total:	54,558	7,488		103,259	6,589					
Clubhouse - Roofing										
Asphalt Shingles		120,522								
Standing Seam Metal Roof										
Clubhouse - Roofing Total:		120,522								

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description										
Clubhouse - Fitness Center										
Carpet Tile	11,996									
Fitness Equip Partial Allowance	5,740	5,912	6,089	6,272	6,460	6,654	6,853	7,059	7,271	7,489
Interior Painting - Fitness					4,961					
Wall Mounted Televisions		4,729								
Clubhouse - Fitness Center Total:	17,735	10,641	6,089	6,272	11,421	6,654	6,853	7,059	7,271	7,489
Clubhouse - Locker Rooms										
Refurbishment Allowance - Locker Rooms				140,489						
Clubhouse - Locker Rooms Total:				140,489						
Clubhouse - Second Floor Components										
Cabinets & Laminate Top - Kitchen									8,071	
Floor Tile - Kitchen									6,786	
Folding Tables & Chairs Allowance									,	
Freezer			7,713							
Ice Machine				6,690						
Interior Wall Painting	13,259					15,370				
Microwave - Kitchen				1,254						
Range - Kitchen								3,765	0.400	
Refrigerator - Kitchen							67.055		8,483	
Refurbishment Allowance - Restooms							67,255			
Vinyl Flooring Window Treatment Allowance				13,380						
Clubhouse - Second Floor Components Total:	13,259		7,713	21,324		15,370	67,255	3,765	23,339	
•	13,239		7,713	21,324		13,370	07,233	3,703	23,339	
Clubhouse - Mechanical Systems										
HVAC Unit 1		15,765								
HVAC Unit 2		37,836								
HVAC Unit 3				40,140						
Clubhouse - Mechanical Systems Total:		53,600		40,140						

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description										
Clubhouse - Elevator										
Elevator Cab Refurbishment										
Elevator Equipment Modernization										
Clubhouse - Elevator Total:										
Lake Pavilion										
Composit Deck & Rails										
Exterior Painting - Pavilion	4,592									
Metal Roof - Pavilion										
Wood Bulkhead										
Wood Repair - Pavilion									37,663	
Lake Pavilion Total:	4,592								37,663	
Lawn Pavilions										
Asphalt Shingles				11,038						
Exterior Painting					10,336					
Lawn Pavilions Total:				11,038	10,336					
Sports Pavilion										
Exterior Painting	6,888									
Metal Roof										
Restroom Refurbishment				14,634						
Water Cooler					4,737					
Sports Pavilion Total:	6,888			14,634	4,737					
Ball Fields										
Chain Link Back Stops								42,354		
Chain Link Dugouts & Roof								30,118		
Chain Link Fencing 4 Ft								34,095		
Chain Link Fencing 6 Ft								19,577		
Ball Fields Total:								126,144		
Basketball Courts										
Basketball Court Resurfacing	16,071					18,631				
Basketball Pole & Backboard										

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description										
Basketball Courts continued										
Chain Link Fencing					29,905					
Light Poles										
Basketball Courts Total:	16,071				29,905	18,631				
Tennis Complex										
Asphalt Shingles - Maintenance Building				12,878						
Exterior Painting - Maintenance Building	4,209									
Exterior Painting - Pavilion	10,714					12,420				
HVAC Unit - Tennis Office					10,336					
Metal Roof - Pavilion										
Refurbishment Allowance - Restrooms				41,812					10.150	
Water Coolers						24.041			10,179	
Wood Pergola - Pavilion Tennis Complex Total:	14.022			54,690	10,336	24,841			10 170	
Tennis Complex Total:	14,923			54,090	10,330	37,261			10,179	
Tennis Courts										
Aluminium Fence - Patio							13,816			
Aluminum Bleachers										
Chain Link Fencing - 10 Ft	109,129									
Chain Link Fencing - 4 Ft										
Light Poles Shade Pavilions				16 705						
Tennis Court Replenishment Allowance	33,672			16,725	37,899				42,655	
Wind Screens	33,072				31,077		20,103		42,033	
Wood Bulkheads							20,103			
Tennis Courts Total:	142,802			16,725	37,899		33,920		42,655	
Swimming Pools - General										
Aluminium Fencing										
Asphalt Shingles - Sidewalk Pavilion				3,679						
Concrete Pavers - Pool Decks				-,0,7						
Exterior Painting - Pool Slide Tower							27,414			
HVAC Unit - Pool Office					6,891					

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description	_							-		
Swimming Pools - General continued										
Lifeguard Chairs										
Light Poles										
Metal Roof - Pool Slide Building										
Pool Furniture Annual Allowance	4,783	4,926	5,074	5,227	5,383	5,545	5,711	5,882	6,059	6,241
Pool Pumps & Equipment Annual Allowance	15,306	15,765	16,238	16,725	17,227	17,743	18,276	18,824	19,389	19,970
Pool Shade Structures										
Pool Slide Railing										
Pool Slide Refurbishment										39,941
Vinyl Fence - Pool Equipment Yard										
Swimming Pools - General Total:	20,089	20,691	21,312	25,631	29,501	23,288	51,400	24,706	25,448	66,152
Family Pool Complex										
Exterior Painting - Pavilion	13,010									
Metal Roof - Pavilion										
Pool Resurfacing		248,296								
Refurbishment Allowance - Restrooms				25,087						
Wood Pergola									108,577	
Family Pool Complex Total:	13,010	248,296		25,087					108,577	
Lap Pool Complex										
Exterior Painting - Pavilion					6,891					
Exterior Painting - Restroom Pavilion	4,305									
Lane Divider Reel									4,702	
Lane Dividers	7,959									
Light Poles										
Metal Roof - Pavilion				54,189						
Metal Roof - Restroom Pavilion				55,527						
Pool Heater Allowance						91,822				
Pool Lift					105 201					
Pool Resurfacing					185,281					
Pool Solar Blanket	2 206				10,853					
Pool Solar Blanket Reel	2,296			22.450						
Refurbishment Allowance - Lap Pool Restrooms				33,450						

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description										
Lap Pool Complex continued										
Starting Platforms										
Water Coolers					4,737					
Lap Pool Complex Total:	14,559			143,165	207,762	91,822			4,702	
Splash Pool										
Pool Play Equipment Allowance										
Pool Resurfacing		44,220								
Splash Pool Total:		44,220								
Playground - Clubhouse										
Bipod Swings - 2 Bay					6,891					
Cresent Climber										
Park Benches			26,386							
Picnic Tables						18,631				
Plastic Play Surface Border										
Play Equipment Allowance										
Speedy Spinner										
Spring Riders					6,891					
Wood Park Benches										
Wood Play Equipment										
Playground - Clubhouse Total:			26,386		13,781	18,631				
Playground - Deerview Park										
Bi-Pod Swing Set										
Cresent Climber										
Gazebo Roof										
Park Benches										
Picnic Tables										
Plastic Play Surface Border				12,776						
Play Equipment Allowance										
Spring Rider										
Vinyl Privacy Fence										
Vinyl Ranch Fence										
Playground - Deerview Park Total:				12,776						

Community Advisors Page 3-25 May 10, 2022

Gazebo Roof Park Bench Picnic Tables Plastic Play Surface Border Play Equipment Allowance Vinyl Privacy Fence Playground - Hamilton Glen Park Total: Playgrounds - Whitfield Park		42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Bi-Pod Swing Set Gazebo Roof Park Bench Picnic Tables Plastic Play Surface Border Play Equipment Allowance Vinyl Privacy Fence Playground - Hamilton Glen Park Total: Bi-Pod Swing Set Gazebo Roof Park Bench Picnic Tables Plastic Play Surface Border 11,415 Play Equipment Allowance Vinyl Privacy Fence Vinyl Ranch Fence Vinyl Ranch Fence	Description										
Bi-Pod Swing Set Gazebo Roof Park Bench Picnic Tables Plastic Play Surface Border Play Equipment Allowance Vinyl Privacy Fence Playground - Hamilton Glen Park Total: Bi-Pod Swing Set Gazebo Roof Park Bench Picnic Tables Plastic Play Surface Border 11,415 Play Equipment Allowance Vinyl Privacy Fence Vinyl Ranch Fence Vinyl Ranch Fence	Playground - Hamilton Glen Park										
Park Bench Picnic Tables Plastic Play Surface Border Play Equipment Allowance Vinyl Privacy Fence Playground - Hamilton Glen Park Total: Playgrounds - Whitfield Park Bi-Pod Swing Set Gazebo Roof Park Bench Picnic Tables Plastic Play Surface Border Playtrace Border Piriot Tables Playtrace Border Playtrace Border Play Surface Border Vinyl Privacy Fence Vinyl Privacy Fence Vinyl Ranch Fence	Bi-Pod Swing Set										
Piantic Tables Plastic Play Surface Border Play Equipment Allowance Vinyl Privacy Fence Playground - Hamilton Glen Park Total: Playgrounds - Whitfield Park Bi-Pod Swing Set Gazebo Roof Park Bench Picnic Tables Plastic Play Surface Border Plastic Play Surface Border Plastic Play Surface Border Vinyl Privacy Fence Vinyl Ranch Fence Vinyl Ranch Fence	Gazebo Roof										
Plastic Play Surface Border Play Equipment Allowance Vinyl Privacy Fence Playground - Hamilton Glen Park Total: Playgrounds - Whitfield Park Bi-Pod Swing Set Gazebo Roof Park Bench Picnic Tables Plastic Play Surface Border Playtic Play Surface Border Playser Surface Border Playser Surface Border Playser Surface Border Playser Surface Border Play Equipment Allowance Vinyl Privacy Fence Vinyl Ranch Fence											
Play Equipment Allowance Vinyl Privacy Fence Playground - Hamilton Glen Park Total: Playgrounds - Whitfield Park Bi-Pod Swing Set Gazebo Roof Park Bench Picnic Tables Plastic Play Surface Border Play Equipment Allowance Vinyl Privacy Fence Vinyl Ranch Fence											
Vinyl Privacy Fence Playground - Hamilton Glen Park Total: 5,268 Playgrounds - Whitfield Park Bi-Pod Swing Set Gazebo Roof Park Bench Picnic Tables Plastic Play Surface Border 11,415 Play Equipment Allowance Vinyl Privacy Fence Vinyl Ranch Fence Vinyl Ranch Fence					5,268						
Playground - Hamilton Glen Park Total: Playgrounds - Whitfield Park Bi-Pod Swing Set Gazebo Roof Park Bench Picnic Tables Plastic Play Surface Border Play Equipment Allowance Vinyl Privacy Fence Vinyl Ranch Fence											
Playgrounds - Whitfield Park Bi-Pod Swing Set Gazebo Roof Park Bench Picnic Tables Plastic Play Surface Border Play Surface Border Vinyl Privacy Fence Vinyl Ranch Fence											
Bi-Pod Swing Set Gazebo Roof Park Bench Picnic Tables Plastic Play Surface Border Play Equipment Allowance Vinyl Privacy Fence Vinyl Ranch Fence	Playground - Hamilton Glen Park Total:				5,268						
Bi-Pod Swing Set Gazebo Roof Park Bench Picnic Tables Plastic Play Surface Border Play Equipment Allowance Vinyl Privacy Fence Vinyl Ranch Fence	Playgrounds - Whitfield Park										
Park Bench Picnic Tables Plastic Play Surface Border Play Equipment Allowance Vinyl Privacy Fence Vinyl Ranch Fence I1,415 Vinyl Ranch Fence	Bi-Pod Swing Set										
Picnic Tables Plastic Play Surface Border Play Equipment Allowance Vinyl Privacy Fence Vinyl Ranch Fence	Gazebo Roof										
Plastic Play Surface Border 11,415 Play Equipment Allowance Vinyl Privacy Fence Vinyl Ranch Fence	Park Bench										
Play Equipment Allowance Vinyl Privacy Fence Vinyl Ranch Fence											
Vinyl Privacy Fence Vinyl Ranch Fence					11,415						
Vinyl Ranch Fence											
<u></u>											
Playgrounds - Whitheld Park Total: 11,415	•				44.44						
	Playgrounds - Whitfield Park Total:				11,415						
Maintenance Shop & Equipment	Maintenance Shop & Equipment										
All Terain Vehicle 19,706	All Terain Vehicle		19,706								
	Exterior Painting	12,627									
Golf Cart											
Jon Boat & Motor Allowance 13,589					13,589						
	Metal Roof										
Maintenance Shop & Equipment Total: 12,627 19,706 13,589	Maintenance Shop & Equipment Total:	12,627	19,706		13,589						
Operating Expense	Operating Expense										
	Flooring - Office	Unfunded									
Furniture - Second Floor Clubhouse Unfunded	Furniture - Second Floor Clubhouse	Unfunded									
Interior Painting - Office Unfunded		Unfunded									
Office Equipment & Furniture Allowance Unfunded	Office Equipment & Furniture Allowance	Unfunded									

Middle Village CDD Income & Expense Spreadsheet

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description										
Operating Expense continued										
Parking Lot Seal Coat	Unfunded									
Steel Trash Cans	Unfunded									
Wood Mulch - Play Areas	Unfunded									
Components Not Included										
Clock Tower Clock	Unfunded									
Fabric Shade Awnings - Tennis Curts	Unfunded									
Year Total:	371,442	525,165	61,500	728,458	914,387	700,888	159,428	189,911	259,833	73,641

Description	Expenditures
Replacement Year 22-23	
Site Components - General	
Decorative Fountain Refurbishment Allowance	3,000
Irrigation System Repair Allowance	3,000
Well 4" Pump - Tennis Courts	4,500
Well 6" Pump - Oakleaf Plantation Parkway	6,200
Well 6" Pump - Plantation Oaks Blvd. West	6,200
Site Components - Monuments	
Exterior Paint - Bell Tower	6,000
Exterior Paint - Clock Tower	6,000
Site Components - Fencing	
Dumpster Enclosure Gates	6,400
Clubhouse - General	
Painting - Guard Rails	3,162
Painting - Monument Stair Rails	4,055
Security Camera System Allowance	15,000
Water Heater	3,060
Clubhouse - Fitness Center	
Carpet Tile	6,270
Fitness Equip Partial Allowance	3,000
Interior Painting - Fitness	2,304
Clubhouse - Second Floor Components	
Folding Tables & Chairs Allowance	3,000
Interior Wall Painting	6,930
Lake Pavilion	,
Exterior Painting - Pavilion	2,400
Sports Pavilion	,
Exterior Painting	3,600
Water Cooler	2,200
Basketball Courts	2,200
Basketball Court Resurfacing	8,400
Basketball Pole & Backboard	7,200
	7,200
Tennis Complex Exterior Painting - Maintenance Building	2,200
Exterior Painting - Pavilion	5,600
Exterior 1 anting - 1 avinon	5,000

Description	Expenditures
Replacement Year 22-23 continued	
HVAC Unit - Tennis Office	4,800
Tennis Courts	
Tennis Court Replenishment Allowance	17,600
Swimming Pools - General	
HVAC Unit - Pool Office	3,200
Lifeguard Chairs	4,200
Pool Furniture Annual Allowance	2,500
Pool Pumps & Equipment Annual Allowance	8,000
Family Pool Complex	
Exterior Painting - Pavilion	6,800
Lap Pool Complex	
Exterior Painting - Restroom Pavilion	2,250
Lane Dividers	4,160
Pool Resurfacing	86,044
Pool Solar Blanket	5,040
Water Coolers	2,200
Playground - Deerview Park	
Bi-Pod Swing Set	3,200
Park Benches	1,200
Picnic Tables	2,600
Play Equipment Allowance	30,000
Spring Rider	1,600
Playground - Hamilton Glen Park	
Bi-Pod Swing Set	3,200
Park Bench	1,300
Picnic Tables	2,600
Play Equipment Allowance	30,000
Playgrounds - Whitfield Park	
Bi-Pod Swing Set	3,200
Park Bench	1,200
Picnic Tables	2,600
Play Equipment Allowance	30,000
Maintenance Shop & Equipment	
Exterior Painting	6,600

Description	Expenditures
Replacement Year 22-23 continued Golf Cart	15 000
	15,000
Total for 2022 - 2023	\$400,775
Replacement Year 23-24	
Clubhouse - Roofing	
Asphalt Shingles	64,830
Clubhouse - Fitness Center	2.100
Fitness Equip Partial Allowance	3,180
Wall Mounted Televisions	2,544
Swimming Pools - General Pool Furniture Annual Allowance	2.650
Pool Furniture Annual Allowance Pool Pumps & Equipment Annual Allowance	2,650 8,480
· · · · ·	0,400
Lap Pool Complex Pool Lift	3,392
Playground - Deerview Park	3,372
Cresent Climber	2,968
Total for 2023 - 2024	\$88,044
Replacement Year 24-25	
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	3,339
Basketball Courts	,
Chain Link Fencing	15,457
Swimming Pools - General	
Pool Furniture Annual Allowance	2,782
Pool Pumps & Equipment Annual Allowance	8,904
Total for 2024 - 2025	\$30,483
Replacement Year 25-26	
Site Components - Monuments	
Brick Tuck Point & Seal - Bell Tower	21,530
Brick Tuck Point & Seal - Clock Tower	24,401
Clubhouse - General	
Exterior Painting - Clubhouse	47,449

Description	Expenditures
Replacement Year 25-26 continued Kitchen Cabinet & Equipment - Snack Bar	9,723
Clubhouse - Fitness Center	9,123
Fitness Equip Partial Allowance	3,473
Clubhouse - Locker Rooms	
Refurbishment Allowance - Locker Rooms	77,785
Clubhouse - Second Floor Components	
Ice Machine	3,704
Microwave - Kitchen	695
Range - Kitchen	1,852
Window Treatment Allowance	7,408
Lawn Pavilions	ć 110
Asphalt Shingles	6,112
Sports Pavilion	0.102
Restroom Refurbishment	8,103
Tennis Complex	7 120
Asphalt Shingles - Maintenance Building Refurbishment Allowance - Restrooms	7,130 23,150
	23,130
Tennis Courts Shade Pavilions	9,260
	9,200
Swimming Pools - General Asphalt Shingles - Sidewalk Pavilion	2,037
Pool Furniture Annual Allowance	2,894
Pool Pumps & Equipment Annual Allowance	9,260
Family Pool Complex	-,
Refurbishment Allowance - Restrooms	13,890
Lap Pool Complex	
Refurbishment Allowance - Lap Pool Restrooms	18,520
Playground - Deerview Park	
Plastic Play Surface Border	7,074
Playground - Hamilton Glen Park	
Plastic Play Surface Border	2,917
Playgrounds - Whitfield Park	
Plastic Play Surface Border	6,320

Description	Expenditures
Replacement Year 25-26 continued	
Maintenance Shop & Equipment Jon Boat & Motor Allowance	7,524
Total for 2025 - 2026	\$322,211
Replacement Year 26-27	
Clubhouse - Fitness Center Fitness Equip Partial Allowance	3,577
Lawn Pavilions Exterior Painting	5,723
Tennis Courts Tennis Court Replenishment Allowance	20,984
Swimming Pools - General	, in the second
Pool Furniture Annual Allowance Pool Pumps & Equipment Annual Allowance	2,981 9,538
Lap Pool Complex	2017
Exterior Painting - Pavilion Pool Solar Blanket Reel	3,815 1,431
Total for 2026 - 2027	\$48,047
Replacement Year 27-28	
Site Components - General Irrigation System Repair Allowance	3,684
Site Components - Parking Lots Parking Lot Mill & Resurface	267,192
Clubhouse - Fitness Center Fitness Equip Partial Allowance	3,684
Clubhouse - Second Floor Components Interior Wall Painting	8,510
Ball Fields	
Chain Link Back Stops Chain Link Dugouts & Roof	22,104 15,719
Chain Link Dugouts & Roof Chain Link Fencing 4 Ft	17,794
Chain Link Fencing 6 Ft	10,217

Description	Expenditures
Replacement Year 27-28 continued	
Basketball Courts	
Basketball Court Resurfacing	10,315
Tennis Complex	
Exterior Painting - Pavilion	6,877
Wood Pergola - Pavilion	13,754
Swimming Pools - General	
Pool Furniture Annual Allowance	3,070
Pool Pumps & Equipment Annual Allowance	9,824
Lap Pool Complex	
Pool Heater Allowance	50,840
Playground - Clubhouse	
Picnic Tables	10,315
Total for 2027 - 2028	\$453,899
Replacement Year 28-29	
Clubhouse - General	
Access Control Panel	4,806
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	3,795
Clubhouse - Second Floor Components	
Refurbishment Allowance - Restooms	37,237
Tennis Courts	
Wind Screens	11,131
Swimming Pools - General	
Exterior Painting - Pool Slide Tower	15,178
Pool Furniture Annual Allowance	3,162
Pool Pumps & Equipment Annual Allowance	10,119
Family Pool Complex	150.252
Pool Resurfacing	159,372
Splash Pool	20, 202
Pool Resurfacing	28,383
Playground - Clubhouse	6.224
Speedy Spinner	6,324

Description	Expenditures
Replacement Year 28-29 continued	
Maintenance Shop & Equipment	
All Terain Vehicle	12,649
Total for 2028 - 2029	\$292,156
Replacement Year 29-30	
Site Components - Signage	
Refurbishment Allowance - Amenity Monument Sign	3,908
Refurbishment Allowance - Deerview Lane entry	3,908
Refurbishment Allowance - Hamilton Glen Entry	3,908
Refurbishment Allowance - Whitfield Entry	3,908
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	3,908
Tennis Courts	
Chain Link Fencing - 4 Ft	7,387
Swimming Pools - General	
Pool Furniture Annual Allowance	3,257
Pool Pumps & Equipment Annual Allowance	10,422
Playground - Clubhouse	
Play Equipment Allowance	58,626
Wood Play Equipment	19,542
Total for 2029 - 2030	\$118,776
Replacement Year 30-31	
Site Components - Parking Lots	
Light Poles	15,029
Light Poles	33,815
Clubhouse - General	
Guard Rail	30,783
Water Coolers	8,454
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	4,026
Interior Painting - Fitness	3,092
Clubhouse - Second Floor Components	
Cabinets & Laminate Top - Kitchen	4,468

Description	Expenditures
Replacement Year 30-31 continued	
Floor Tile - Kitchen	3,757
Clubhouse - Elevator	
Elevator Cab Refurbishment	11,540
Lake Pavilion	20.052
Wood Repair - Pavilion	20,853
Basketball Courts	16.600
Light Poles	16,639
Tennis Courts	04.460
Light Poles Tannia Court Panlanishment Allawanaa	94,469
Tennis Court Replenishment Allowance	23,617
Swimming Pools - General	14.402
Light Poles Pool Furniture Annual Allowance	14,492 3,355
Pool Pumps & Equipment Annual Allowance	10,735
Pool Slide Railing	17,176
Family Pool Complex	,
Wood Pergola	60,116
Lap Pool Complex	·
Lane Divider Reel	2,603
Pool Solar Blanket	6,763
Starting Platforms	21,739
Splash Pool	
Pool Play Equipment Allowance	53,675
Playground - Clubhouse	
Park Benches	17,444
Playground - Deerview Park	
Vinyl Ranch Fence	14,879
Total for 2030 - 2031	\$493,520
Replacement Year 31-32	
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	4,146
Clubhouse - Mechanical Systems	
HVAC Unit 1	11,057

Description	Expenditures
Replacement Year 31-32 continued HVAC Unit 2	26,537
Swimming Pools - General	,
Pool Furniture Annual Allowance	3,455
Pool Pumps & Equipment Annual Allowance	11,057
Pool Slide Refurbishment	22,114
Playground - Clubhouse	4 422
Bipod Swings - 2 Bay	4,423
Spring Riders	4,423
Total for 2031 - 2032	\$87,213
Replacement Year 32-33	
Site Components - General	
Decorative Fountain Refurbishment Allowance	4,271
Irrigation System Repair Allowance	4,271
Clubhouse - General	4.504
Painting - Guard Rails	4,501 5,772
Painting - Monument Stair Rails Security Camera System Allowance	5,772 21,354
Clubhouse - Fitness Center	21,334
Carpet Tile	8,926
Fitness Equip Partial Allowance	4,271
Clubhouse - Second Floor Components	
Freezer	5,410
Interior Wall Painting	9,866
Lake Pavilion	
Exterior Painting - Pavilion	3,417
Sports Pavilion	
Exterior Painting	5,125
Basketball Courts	11.050
Basketball Court Resurfacing	11,958
Tennis Complex	2 122
Exterior Painting - Maintenance Building Exterior Painting - Pavilion	3,132
	7,972
Swimming Pools - General Pool Furniture Annual Allowance	3,559
1 0011 Grintare / Hillaut / Hie wallee	3,337

Description	Expenditures
Replacement Year 32-33 continued	
Pool Pumps & Equipment Annual Allowance	11,389
Family Pool Complex	
Exterior Painting - Pavilion	9,681
Lap Pool Complex	
Exterior Painting - Restroom Pavilion	3,203
Lane Dividers	5,922
Maintenance Shop & Equipment	0.206
Exterior Painting	9,396
Total for 2032 - 2033	\$143,395
Replacement Year 33-34	
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	4,399
Wall Mounted Televisions	3,519
Clubhouse - Mechanical Systems	
HVAC Unit 3	28,153
Lake Pavilion	
Wood Bulkhead	15,953
Tennis Courts	
Aluminum Bleachers	3,812
Swimming Pools - General	
Pool Furniture Annual Allowance	3,666
Pool Pumps & Equipment Annual Allowance	11,730
Total for 2033 - 2034	\$71,233
Replacement Year 34-35	
Site Components - General	
Well 4" Pump - Tennis Courts	6,796
Well 6" Pump - Oakleaf Plantation Parkway	9,364
Well 6" Pump - Plantation Oaks Blvd. West	9,364
Site Components - Monuments	0.0
Exterior Paint - Bell Tower	9,062
Exterior Paint - Clock Tower	9,062

Description	Expenditures
Replacement Year 34-35 continued	
Clubhouse - General	
Water Heater	4,622
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	4,531
Sports Pavilion	
Water Cooler	3,323
Tennis Complex	
HVAC Unit - Tennis Office	7,249
Tennis Courts	
Tennis Court Replenishment Allowance	26,581
Swimming Pools - General	
HVAC Unit - Pool Office	4,833
Pool Furniture Annual Allowance	3,776
Pool Pumps & Equipment Annual Allowance	12,082
Lap Pool Complex	
Pool Resurfacing	129,952
Water Coolers	3,323
Playground - Clubhouse	
Cresent Climber	3,172
Total for 2034 - 2035	\$247,091
Replacement Year 35-36	
Site Components - Fencing	
Vinyl Fencing - Deerview	356,857
Vinyl Fencing - Hamilton Glen	116,991
Vinyl Fencing - Whitfield	183,251
Site Components - Parking Lots	10.110
Concrete Pavers - Parking Lot	10,143
Clubhouse - General	10 - 10
Exterior Painting - Clubhouse	63,768
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	4,667
Clubhouse - Second Floor Components	
Microwave - Kitchen	933

Description	Expenditures
Replacement Year 35-36 continued	
Refrigerator - Kitchen	5,445
Tennis Complex	
Water Coolers	6,534
Tennis Courts	
Wood Bulkheads	37,521
Swimming Pools - General	
Aluminium Fencing	47,378
Concrete Pavers - Pool Decks	168,644
Metal Roof - Pool Slide Building	22,401
Pool Furniture Annual Allowance	3,889
Pool Pumps & Equipment Annual Allowance	12,445
Vinyl Fence - Pool Equipment Yard	6,944
Family Pool Complex	7 0.006
Metal Roof - Pavilion	79,996
Lap Pool Complex	
Light Poles	28,001
Playground - Deerview Park	
Gazebo Roof	7,467
Vinyl Privacy Fence	9,645
Playground - Hamilton Glen Park	
Gazebo Roof	7,467
Vinyl Privacy Fence	11,429
Playgrounds - Whitfield Park	
Gazebo Roof	7,467
Vinyl Privacy Fence	20,543
Vinyl Ranch Fence	18,481
Total for 2035 - 2036	\$1,238,305
Replacement Year 36-37	
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	4,807
Lawn Pavilions	
Exterior Painting	7,691
Swimming Pools - General	
Pool Furniture Annual Allowance	4,006

Description	Expenditures
Replacement Year 36-37 continued	12.010
Pool Pumps & Equipment Annual Allowance	12,818
Lap Pool Complex Exterior Painting - Pavilion	5,127
Playground - Clubhouse	
Plastic Play Surface Border	16,487
Wood Park Benches	2,884
Total for 2036 - 2037	\$53,821
Replacement Year 37-38	
Site Components - General	
Irrigation System Repair Allowance	4,951
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	4,951
Clubhouse - Second Floor Components	
Folding Tables & Chairs Allowance	4,951
Interior Wall Painting	11,437
Range - Kitchen	2,641
Vinyl Flooring	24,887
Basketball Courts	12.052
Basketball Court Resurfacing	13,863
Basketball Pole & Backboard	11,882
Tennis Complex	0.242
Exterior Painting - Pavilion	9,242
Swimming Pools - General	
Lifeguard Chairs	6,931
Pool Furniture Annual Allowance	4,126
Pool Pumps & Equipment Annual Allowance	13,203
Lap Pool Complex	69.224
Pool Heater Allowance	68,324
Playground - Deerview Park	£ 201
Bi-Pod Swing Set Play Equipment Allowance	5,281 49,510
Spring Rider	2,641
1 0	2,041
Playground - Hamilton Glen Park Bi-Pod Swing Set	5,281
DEI OU DWING DEI	3,201

Description	Expenditures
Replacement Year 37-38 continued	
Play Equipment Allowance	49,510
Playgrounds - Whitfield Park	
Bi-Pod Swing Set	5,281
Play Equipment Allowance	49,510
Maintenance Shop & Equipment	
Golf Cart	24,755
Total for 2037 - 2038	\$373,160
Replacement Year 38-39	
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	5,100
Interior Painting - Fitness	3,916
Tennis Courts	
Tennis Court Replenishment Allowance	29,917
Wind Screens	14,959
Swimming Pools - General	
Exterior Painting - Pool Slide Tower	20,398
Pool Furniture Annual Allowance	4,250
Pool Pumps & Equipment Annual Allowance	13,599
Pool Shade Structures	33,997
Lap Pool Complex Pool Lift	5 440
Pool Solar Blanket	5,440 8,567
	0,507
Playground - Deerview Park Park Benches	2,040
Picnic Tables	4,420
	1,120
Playground - Hamilton Glen Park Park Bench	2,210
Picnic Tables	4,420
Playgrounds - Whitfield Park	.,.20
Park Bench	2,040
Picnic Tables	4,420
Total for 2038 - 2039	\$159,691
IOMI IOI MUJU - MUJ/	Ψ137,071

Description	Expenditures
Replacement Year 39-40	
Site Components - Signage	
Refurbishment Allowance - Amenity Monument Sign	5,253
Refurbishment Allowance - Deerview Lane entry	5,253
Refurbishment Allowance - Hamilton Glen Entry	5,253
Refurbishment Allowance - Whitfield Entry	5,253
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	5,253
Swimming Pools - General	
Pool Furniture Annual Allowance	4,377
Pool Pumps & Equipment Annual Allowance	14,007
Total for 2039 - 2040	\$44,647
Replacement Year 40-41	
Site Components - Monuments	
Metal Roof - Bell Tower	14,699
Metal Roof - Clock Tower	14,699
Clubhouse - General	
Monument Stair Railings	64,474
Clubhouse - Roofing	
Standing Seam Metal Roof	89,448
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	5,410
Clubhouse - Elevator	
Elevator Equipment Modernization	56,265
Lake Pavilion	
Metal Roof - Pavilion	18,467
Wood Repair - Pavilion	28,025
Sports Pavilion	
Metal Roof	25,103
Tennis Complex	
Metal Roof - Pavilion	58,603
Swimming Pools - General	
Pool Furniture Annual Allowance	4,508

Description	Expenditures
Replacement Year 40-41 continued Pool Pumps & Equipment Annual Allowance	14,427
Playground - Clubhouse Speedy Spinner	9,017
Maintenance Shop & Equipment Metal Roof	88,178
Total for 2040 - 2041	\$491,323
Replacement Year 41-42	
Clubhouse - Fitness Center Fitness Equip Partial Allowance	5,572
Lake Pavilion Composit Deck & Rails	21,993
Swimming Pools - General	21,773
Pool Furniture Annual Allowance	4,644
Pool Pumps & Equipment Annual Allowance	14,860
Pool Slide Refurbishment	29,720
Playground - Clubhouse Play Equipment Allowance	83,587
Wood Play Equipment	27,862
Playground - Deerview Park	
Cresent Climber	5,201
Total for 2041 - 2042	\$193,438
Replacement Year 42-43	
Site Components - General	
Decorative Fountain Refurbishment Allowance	5,740
Irrigation System Repair Allowance	5,740
Site Components - Fencing Chain Link Farms Maintenas Shad	16.607
Chain Link Fence - Maintence Shed Dumpster Enclosure Gates	16,607 12,245
Clubhouse - General	12,2 13
Painting - Guard Rails	6,050
Painting - Monument Stair Rails	7,758

Description	Expenditures
Replacement Year 42-43 continued	
Security Camera System Allowance	28,698
Water Coolers	12,053
Clubhouse - Fitness Center	
Carpet Tile	11,996
Fitness Equip Partial Allowance	5,740
Clubhouse - Second Floor Components	
Interior Wall Painting	13,259
Lake Pavilion	
Exterior Painting - Pavilion	4,592
Sports Pavilion	
Exterior Painting	6,888
Basketball Courts	
Basketball Court Resurfacing	16,071
Tennis Complex	
Exterior Painting - Maintenance Building	4,209
Exterior Painting - Pavilion	10,714
Tennis Courts	
Chain Link Fencing - 10 Ft	109,129
Tennis Court Replenishment Allowance	33,672
Swimming Pools - General	
Pool Furniture Annual Allowance	4,783
Pool Pumps & Equipment Annual Allowance	15,306
Family Pool Complex	10.010
Exterior Painting - Pavilion	13,010
Lap Pool Complex	
Exterior Painting - Restroom Pavilion	4,305
Lane Dividers	7,959
Pool Solar Blanket Reel	2,296
Maintenance Shop & Equipment	12 (27
Exterior Painting	12,627
Total for 2042 - 2043	\$371,442
Replacement Year 43-44	
Clubhouse - General	- 400
Access Control Panel	7,488

Description	Expenditures
Replacement Year 43-44 continued	
Clubhouse - Roofing	
Asphalt Shingles	120,522
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	5,912
Wall Mounted Televisions	4,729
Clubhouse - Mechanical Systems	
HVAC Unit 1	15,765
HVAC Unit 2	37,836
Swimming Pools - General	
Pool Furniture Annual Allowance	4,926
Pool Pumps & Equipment Annual Allowance	15,765
Family Pool Complex	
Pool Resurfacing	248,296
Splash Pool	
Pool Resurfacing	44,220
Maintenance Shop & Equipment	
All Terain Vehicle	19,706
Total for 2043 - 2044	\$525,165
Replacement Year 44-45	
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	6,089
Clubhouse - Second Floor Components	
Freezer	7,713
Swimming Pools - General	
Pool Furniture Annual Allowance	5,074
Pool Pumps & Equipment Annual Allowance	16,238
Playground - Clubhouse	
Park Benches	26,386
Total for 2044 - 2045	\$61,500
Replacement Year 45-46	
Site Components - Monuments	
Brick Tuck Point & Seal - Bell Tower	38,885

Description	Expenditures
Replacement Year 45-46 continued	
Brick Tuck Point & Seal - Clock Tower	44,070
Clubhouse - General	
Exterior Painting - Clubhouse	85,698
Kitchen Cabinet & Equipment - Snack Bar	17,561
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	6,272
Clubhouse - Locker Rooms	
Refurbishment Allowance - Locker Rooms	140,489
Clubhouse - Second Floor Components	
Ice Machine	6,690
Microwave - Kitchen	1,254
Window Treatment Allowance	13,380
Clubhouse - Mechanical Systems	
HVAC Unit 3	40,140
Lawn Pavilions	
Asphalt Shingles	11,038
Sports Pavilion	
Restroom Refurbishment	14,634
Tennis Complex	
Asphalt Shingles - Maintenance Building	12,878
Refurbishment Allowance - Restrooms	41,812
Tennis Courts	
Shade Pavilions	16,725
Swimming Pools - General	
Asphalt Shingles - Sidewalk Pavilion	3,679
Pool Furniture Annual Allowance	5,227
Pool Pumps & Equipment Annual Allowance	16,725
Family Pool Complex	
Refurbishment Allowance - Restrooms	25,087
Lap Pool Complex	
Metal Roof - Pavilion	54,189
Metal Roof - Restroom Pavilion	55,527
Refurbishment Allowance - Lap Pool Restrooms	33,450

Description	Expenditures
Replacement Year 45-46 continued	
Playground - Deerview Park	
Plastic Play Surface Border	12,776
Playground - Hamilton Glen Park	5.260
Plastic Play Surface Border	5,268
Playgrounds - Whitfield Park Plastic Play Surface Border	11,415
Maintenance Shop & Equipment	11,413
Jon Boat & Motor Allowance	13,589
Total for 2045 - 2046	\$728,458
	,
Replacement Year 46-47	
Site Components - General Well 4" Purpos Tempis Courts	0.600
Well 4" Pump - Tennis Courts Well 6" Pump - Oakleaf Plantation Parkway	9,690 13,351
Well 6" Pump - Plantation Oaks Blvd. West	13,351
Wood Boardwalk Replacement	307,149
Site Components - Monuments	
Exterior Paint - Bell Tower	12,920
Exterior Paint - Clock Tower	12,920
Site Components - Fencing	102 740
Aluminum Fence 8 Ft - Amenity	182,740
Clubhouse - General Water Heater	6,589
Clubhouse - Fitness Center	0,369
Fitness Equip Partial Allowance	6,460
Interior Painting - Fitness	4,961
Lawn Pavilions	
Exterior Painting	10,336
Sports Pavilion	
Water Cooler	4,737
Basketball Courts Chain Link Famina	20.005
Chain Link Fencing Tannia Complex	29,905
Tennis Complex HVAC Unit - Tennis Office	10,336
11 VAC UIII - TUIIIIS UIIICU	10,550

Replacement Year 46-47 continued Tennis Courts Tennis Court Replenishment Allowance 37,899 Swimming Pools - General HVAC Unit - Pool Office 6,891 Pool Furniture Annual Allowance 5,383 Pool Pumps & Equipment Annual Allowance 17,227
Tennis Court Replenishment Allowance 37,899 Swimming Pools - General HVAC Unit - Pool Office 6,891 Pool Furniture Annual Allowance 5,383
Swimming Pools - General HVAC Unit - Pool Office 6,891 Pool Furniture Annual Allowance 5,383
HVAC Unit - Pool Office6,891Pool Furniture Annual Allowance5,383
Pool Furniture Annual Allowance 5,383
,
Pool Pumps & Equipment Annual Allowance 17,227
Lap Pool Complex
Exterior Painting - Pavilion 6,891
Pool Resurfacing 185,281
Pool Solar Blanket 10,853
Water Coolers 4,737
Playground - Clubhouse
Bipod Swings - 2 Bay 6,891
Spring Riders 6,891
Total for 2046 - 2047 \$914,387
Replacement Year 47-48
Site Components - General
Irrigation System Repair Allowance 6,654
Site Components - Parking Lots
Parking Lot Mill & Resurface 482,578
Clubhouse - Fitness Center
Fitness Equip Partial Allowance 6,654
Clubhouse - Second Floor Components
Interior Wall Painting 15,370
Basketball Courts
Basketball Court Resurfacing 18,631
Tennis Complex
Exterior Painting - Pavilion 12,420
Wood Pergola - Pavilion 24,841
Swimming Pools - General
Pool Furniture Annual Allowance 5,545
Pool Pumps & Equipment Annual Allowance 17,743

Description	Expenditures
Replacement Year 47-48 continued	
Lap Pool Complex	
Pool Heater Allowance	91,822
Playground - Clubhouse	
Picnic Tables	18,631
Total for 2047 - 2048	\$700,888
Replacement Year 48-49	
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	6,853
Clubhouse - Second Floor Components	
Refurbishment Allowance - Restooms	67,255
Tennis Courts	
Aluminium Fence - Patio	13,816
Wind Screens	20,103
Swimming Pools - General	
Exterior Painting - Pool Slide Tower	27,414
Pool Furniture Annual Allowance	5,711
Pool Pumps & Equipment Annual Allowance	18,276
Total for 2048 - 2049	\$159,428
Replacement Year 49-50	
Site Components - Signage	
Refurbishment Allowance - Amenity Monument Sign	7,059
Refurbishment Allowance - Deerview Lane entry	7,059
Refurbishment Allowance - Hamilton Glen Entry	7,059
Refurbishment Allowance - Whitfield Entry	7,059
Clubhouse - Fitness Center	7.050
Fitness Equip Partial Allowance	7,059
Clubhouse - Second Floor Components	2.765
Range - Kitchen	3,765
Ball Fields	40.054
Chain Link Back Stops Chain Link Duggets & Roof	42,354
Chain Link Dugouts & Roof	30,118


Description	Expenditures
Replacement Year 49-50 continued	
Chain Link Fencing 4 Ft	34,095
Chain Link Fencing 6 Ft	19,577
Swimming Pools - General	
Pool Furniture Annual Allowance	5,882
Pool Pumps & Equipment Annual Allowance	18,824
Total for 2049 - 2050	\$189,911
Replacement Year 50-51	
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	7,271
Clubhouse - Second Floor Components	
Cabinets & Laminate Top - Kitchen	8,071
Floor Tile - Kitchen	6,786
Refrigerator - Kitchen	8,483
Lake Pavilion	
Wood Repair - Pavilion	37,663
Tennis Complex	
Water Coolers	10,179
Tennis Courts	
Tennis Court Replenishment Allowance	42,655
Swimming Pools - General	
Pool Furniture Annual Allowance	6,059
Pool Pumps & Equipment Annual Allowance	19,389
Family Pool Complex	
Wood Pergola	108,577
Lap Pool Complex	
Lane Divider Reel	4,702
Total for 2050 - 2051	\$259,833
Replacement Year 51-52	
Clubhouse - Fitness Center	
Fitness Equip Partial Allowance	7,489
Swimming Pools - General	
Pool Furniture Annual Allowance	6,241

Description	Expenditures
Replacement Year 51-52 continued	
Pool Pumps & Equipment Annual Allowance	19,970
Pool Slide Refurbishment	39,941
Total for 2051 - 2052	\$73,641

Middle Village CDD

Orange Park, Florida

Asset Current Cost by Category



		4	detit		ent	. G		
Description	000 cst	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	గ స్తా ప్రత్		Szidza Szidza	gar Sais	عرفة المنافعة	Carlos Cos
Description	2, %	かった	, V.	\$.	Ç	$\mathcal{N}_{\mathbf{r}}$	N G	0.0
Site Components - General	2006	22.22	10	0	0	1.1. 0	2 000 00	2 000
Decorative Fountain Refurbishment Allowa.		22-23	10	0	0	1 Lump Sum	3,000.00	3,000
Irrigation System Repair Allowance	2012 2006	22-23 22-23	5 12	0	0	1 Lump Sum	3,000.00	3,000
Well 4" Pump - Tennis Courts Well 6" Pump - Oakleaf Plantation Parkway		22-23	12	0 2	0	1 Lump Sum 1 Each	4,500.00 6,200.00	4,500 6,200
Well 6" Pump - Plantation Oaks Blvd. West	2006	22-23	12	3	0	1 Lump Sum	6,200.00	6,200
Wood Boardwalk Replacement	2022	46-47	25	0	24	3,479 Square Feet	41.00	142,639
Site Components - General - Total	2022	40 47	23	O	24	5,477 Square 1 cet	41.00	\$165,539
Site Components - Monuments								
Brick Tuck Point & Seal - Bell Tower	2006	25-26	20	0	3	3,000 Square Feet	6.20	18,600
Brick Tuck Point & Seal - Clock Tower	2006	25-26	20	0	3	3,400 Square Feet	6.20	21,080
Exterior Paint - Bell Tower	2006	22-23	12	0	0	1,200 Square Feet	5.00	6,000
Exterior Paint - Clock Tower	2006	22-23	12	0	0	1,200 Square Feet	5.00	6,000
Metal Roof - Bell Tower	2006	40-41	35	0	18	429 Square Feet	19.00	8,151
Metal Roof - Clock Tower	2006	40-41	35	0	18	429 Square Feet	19.00	8,151
Site Components - Monuments - Total								\$67,982
Site Components - Signage								
Refurbishment Allowance - Amenity Monu	2020	29-30	10	0	7	1 Lump Sum	3,000.00	3,000
Refurbishment Allowance - Deerview Lane .	. 2020	29-30	10	0	7	1 Lump Sum	3,000.00	3,000
Refurbishment Allowance - Hamilton Glen .		29-30	10	0	7	1 Lump Sum	3,000.00	3,000
Refurbishment Allowance - Whitfield Entry	2020	29-30	10	0	7	1 Lump Sum	3,000.00	3,000
Site Components - Signage - Total								\$12,000
Site Components - Fencing								
Aluminum Fence 8 Ft - Amenity	2022	46-47	25	0	24	884 Linear Feet	96.00	84,864
Chain Link Fence - Maintence Shed	2019	42-43	24	0	20	280 Linear Feet	31.00	8,680
Dumpster Enclosure Gates	2006	22-23	20	-3	0	4 EA	1,600.00	6,400
Vinyl Fencing - Deerview	2006	35-36	30	0	13	7,400 Linear Feet	31.00	229,400
Vinyl Fencing - Hamilton Glen	2006	35-36	30	0	13	2,426 Linear Feet	31.00	75,206
Vinyl Fencing - Whitfield	2006	35-36	30	0	13	3,800 Linear Feet	31.00	117,800
Site Components - Fencing - Total								\$522,350
Site Components - Parking Lots								
Concrete Pavers - Parking Lot	2006	35-36	30	0	13	800 Square Feet	8.15	6,520
Light Poles	2006	30-31	25	0	8	8 Each	1,400.00	11,200
Light Poles	2006	30-31	25	0	8	14 EA	1,800.00	25,200
Parking Lot Mill & Resurface	2006	27-28	20	2	5	12,724 Square Yards	17.10	217,580
Site Components - Parking Lots - Total								\$260,500
Clubhouse - General								
Access Control Panel	2014	28-29	15	0	6	1 Each	3,800.00	3,800
Exterior Painting - Clubhouse	2006	25-26	10	10	3	14,640 Square Feet	2.80	40,992
Guard Rail	2006	30-31	25	0	8	310 Linear Feet	74.00	22,940

			ZÖĞ		, di	\$0		
	00 05 55 50 50 50 50 50 50 50 50 50 50 5	ç ^e zgé	ک ک	ک. خ	Staga Staga	igiti t	ax. Xi	Chi Cos
Description	Jug Ger	, 5 _{68,} 76	18 2°	A A	€eg.	Jilis .	Jill Cost	Cast Cost
Clubhouse - General continued								
Kitchen Cabinet & Equipment - Snack Bar	2006	25-26	20	0	3	1 Lump Sum	8,400.00	8,400
Monument Stair Railings	2006	40-41	35	0	18	436 Linear Feet	82.00	35,752
Painting - Guard Rails	2012	22-23	10	0	0	340 Linear Feet	9.30	3,162
Painting - Monument Stair Rails	2006	22-23	10	1	0	436 Linear Feet	9.30	4,055
Security Camera System Allowance	2010	22-23	10	0	0	1 Lump Sum	15,000.00	15,000
Water Coolers Water Heater	2019	30-31	12 12	0	8	3 Each	2,100.00	6,300
Clubhouse - General - Total	2006	22-23	12	Ü	0	85 Gallon	36.00	3,060 \$143,461
Ciubilouse - General - Total								\$143,401
Clubhouse - Roofing								
Asphalt Shingles	2006	23-24	20	-2	1	139 Squares	440.00	61,160
Standing Seam Metal Roof	2006	40-41	35	0	18	3,100 Square Feet	16.00	49,600
Clubhouse - Roofing - Total								\$110,760
Clubhouse - Fitness Center								
Carpet Tile	2013	22-23	10	0	0	165 SY	38.00	6,270
Fitness Equip Partial Allowance	2013	22-23	10	0	0	1 Lump Sum	3,000.00	3,000
Interior Painting - Fitness	2013	22-23	8	0	0	1,152 Square Feet	2.00	2,304
Wall Mounted Televisions	2014	23-24	10	0	1	3 Each	800.00	2,400
Clubhouse - Fitness Center - Total								\$13,974
Clubhouse - Locker Rooms								
Refurbishment Allowance - Locker Rooms	2006	25-26	20	0	3	1,400 Square Feet	48.00	67,200
Clubhouse - Locker Rooms - Total	2000	25 26	_0	Ü	J	1, 100 Square 1 cet	10.00	\$67,200
	_							
Clubhouse - Second Floor Compon		20.21	20	_	0	10.11	10500	2 220
Cabinets & Laminate Top - Kitchen	2006	30-31	20	5	8	18 Linear Feet	185.00	3,330
Floor Tile - Kitchen	2006	30-31	20	5	8	200 Square Feet	14.00	2,800
Folding Tables & Chairs Allowance Freezer	2006 2021	22-23 32-33	15 12	0	0 10	1 LS 1 Each	3,000.00 3,800.00	3,000 3,800
Ice Machine	2021	25-26	20	0	3	1 Each	3,200.00	3,200
Interior Wall Painting	2006	22-23	5	12	0	6,300 Square Feet	1.10	6,930
Microwave - Kitchen	2016	25-26	10	0	3	1 Each	600.00	600
Range - Kitchen	2006	25-26	12	8	3	1 Each	1,600.00	1,600
Refrigerator - Kitchen	2021	35-36	15	0	13	1 Each	3,500.00	3,500
Refurbishment Allowance - Restooms	2006	28-29	20	3	6	460 Square Feet	64.00	29,440
Vinyl Flooring	2018	37-38	20	0	15	2,600 Square Feet	5.80	15,080
Window Treatment Allowance	2006	25-26	20	0	3	16 Each	400.00	6,400
Clubhouse - Second Floor Components -	Total							\$79,680
Clubhouse - Mechanical Systems								
HVAC Unit 1	2020	31-32	12	0	9	5 Tons	1,600.00	8,000
	2020	3112				2 1003		(),(),()
HVAC Unit 2	2020 2020			0				
HVAC Unit 2 HVAC Unit 3	2020 2020 2022	31-32 31-32 33-34	12 12		9 11	12 Tons 12 Tons	1,600.00 1,600.00	19,200 _19,200

		4	gent .		ent.	. 50°		
Description	Og Seria	ية ماريخ	, is (2)		a Segui	gi Silis	Jill Cost	Catalais Catalais
-	1 2	~ ~	~ ~	ζ,	*	\sim	\sim 0	0 0
Clubhouse - Elevator Elevator Cab Refurbishment	2006	30-31	25	0	8	1 Lump Sum	8,600.00	8,600
Elevator Equipment Modernization	2006	40-41	25 35	0	8 18	2 Stops	15,600.00	_31,200
Clubhouse - Elevator - Total	2000	.0 .1		Ü	10	2 Stops	10,000.00	\$39,800
Lake Pavilion								
Composit Deck & Rails	2022	41-42	20	0	19	740 Square Feet	16.00	11,840
Exterior Painting - Pavilion	2006	22-23	10	0	0	1,200 Square Feet	2.00	2,400
Metal Roof - Pavilion	2006	40-41	35	0	18	640 Square Feet	16.00	10,240
Wood Bulkhead	2006	33-34	28	0	11	160 Square Feet	68.00	10,880
Wood Repair - Pavilion Lake Pavilion - Total	2021	30-31	10	0	8	740 Square Feet	21.00	<u>15,540</u> \$50,900
Lawn Pavilions								
Asphalt Shingles	2006	25-26	20	0	3	12 Squares	440.00	5,280
Exterior Painting	2017	26-27	10	0	4	2,400 Square Feet	2.00	4,800
Lawn Pavilions - Total						•		\$10,080
Sports Pavilion								
Exterior Painting	2006	22-23	10	4	0	1,800 Square Feet	2.00	3,600
Metal Roof	2006	40-41	35	0	18	870 Square Feet	16.00	13,920
Restroom Refurbishment	2006	25-26	20	0	3	2 Each	3,500.00	7,000
Water Cooler Sports Position Total	2006	22-23	12	0	0	2 Each	1,100.00	$\frac{2,200}{$26,720}$
Sports Pavilion - Total								\$20,720
Ball Fields								
Chain Link Back Stops	2006	27-28	22	0	5	2 Each	9,000.00	18,000
Chain Link Dugouts & Roof	2006	27-28	22	0	5	4 Each	3,200.00	12,800
Chain Link Fencing 4 Ft	2006	27-28	22	0	5	805 Linear Feet	18.00	14,490
Chain Link Fencing 6 Ft Ball Fields - Total	2006	27-28	22	0	5	320 Linear Feet	26.00	\$320 \$53,610
Postrothall Counts								
Basketball Courts Basketball Court Resurfacing	2013	22-23	5	0	0	1,200 Each	7.00	8,400
Basketball Pole & Backboard	2006	22-23	15	0	0	4 EA	1,800.00	7,200
Chain Link Fencing	2006	24-25	22	-3	2	448 LF	31.00	13,888
Light Poles	2006	30-31	25	0	8	4 EA	3,100.00	12,400
Basketball Courts - Total							.,	\$41,888
Tennis Complex								
Asphalt Shingles - Maintenance Building	2006	25-26	20	0	3	14 Squares	440.00	6,160
Exterior Painting - Maintenance Building	2006	22-23	10	7	0	1,100 Square Feet	2.00	2,200
Exterior Painting - Pavilion	2006	22-23	5	10	0	2,800 Square Feet	2.00	5,600
HVAC Unit - Tennis Office	2006	22-23	12	0	0	3 Tons	1,600.00	4,800
Metal Roof - Pavilion	2006	40-41	35	0	18	2,031 SF	16.00	32,496

			rent.			&		
	00 80 50 50 50 50 50 50 50 50 50 50 50 50 50	ද් _ව [%] ල්	gent Jesti	۶. ۶		jarik.	.x. x	Cata Cos
Description	Our con	€8,76	3° 5°	₽	500	Silis	Jit Ost	Car. Cos
Tennis Complex continued								
Refurbishment Allowance - Restrooms	2006	25-26	20	0	3	1 Lump Sum	20,000.00	20,000
Water Coolers	2021	35-36	15	0	13	2 Each	2,100.00	4,200
Wood Pergola - Pavilion Tennis Complex - Total	2006	27-28	20	2	5	400 Square Feet	28.00	11,200 \$86,656
•								700,000
Tennis Courts								
Aluminium Fence - Patio	2019	48-49	30	0	26	168 Linear Feet	36.00	6,048
Aluminum Bleachers	2006	33-34	28	0	11	1 Unit	2,600.00	2,600
Chain Link Fencing - 10 Ft	2019	42-43	24	0	20	1,840 Linear Feet	31.00	57,040
Chain Link Fencing - 4 Ft	2006	29-30	24	0	7	270 Linear Feet	21.00	5,670
Light Poles	2006	30-31	25	0	8	16 Each	4,400.00	70,400
Shade Pavilions	2006	25-26	20	0	3	2 Each	4,000.00	8,000
Tennis Court Replenishment Allowance	2014	22-23	4	1	0	8 Each	2,200.00	17,600
Wind Screens	2019	28-29	10	0	6	8 Courts	1,100.00	8,800
Wood Bulkheads	2006	35-36	30	0	13	670 Linear Feet	36.00	24,120
Tennis Courts - Total								\$200,278
Swimming Pools - General								
Aluminium Fencing	2006	35-36	30	0	13	846 Linear Feet	36.00	30,456
Asphalt Shingles - Sidewalk Pavilion	2006	25-26	20	0	3	4 Squares	440.00	1,760
Concrete Pavers - Pool Decks	2006	35-36	30	0	13	13,384 Square Feet	8.10	108,410
Exterior Painting - Pool Slide Tower	2019	28-29	10	0	6	1 Lump Sum	12,000.00	12,000
HVAC Unit - Pool Office	2006	22-23	12	0	0	2 Tons	1,600.00	3,200
Lifeguard Chairs	2006	22-23	15	0	0	3 Each	1,400.00	4,200
Light Poles	2006	30-31	25	0	8	6 Each	1,800.00	10,800
Metal Roof - Pool Slide Building	2006	35-36	30	0	13	900 Square Feet	16.00	14,400
Pool Furniture Annual Allowance	2006	22-23	1	0	0	1 Lump Sum	2,500.00	2,500
Pool Pumps & Equipment Annual Allowa		22-23	1	0	0	1 Lump Sum	8,000.00	8,000
Pool Shade Structures	2019	38-39	20	0	16	1 Lump Sum	20,000.00	20,000
Pool Slide Railing	2006	30-37	25	0	8	200 Linear Feet	64.00	12,800
Pool Slide Refurbishment	2022	31-32	10	0	9	1 Lump Sum	16,000.00	16,000
Vinyl Fance Pool Equipment Vard	2006	35 36	30	(1)		1/1/ Lingar Foot	31.00	1 161
Vinyl Fence - Pool Equipment Yard	2006	35-36	30	0	13	144 Linear Feet	31.00	<u>4,464</u> \$248,000
Vinyl Fence - Pool Equipment Yard Swimming Pools - General - Total	2006	35-36	30	0	13	144 Linear Feet	31.00	4,464 \$248,990
	2006	35-36	30	0	13	144 Linear Feet	31.00	
Swimming Pools - General - Total	2006	35-36 22-23	30 10	5	0	144 Linear Feet3,400 Square Feet	31.00 2.00	
Swimming Pools - General - Total Family Pool Complex								\$248,990
Swimming Pools - General - Total Family Pool Complex Exterior Painting - Pavilion	2006	22-23	10	5	0	3,400 Square Feet	2.00	\$248,990 6,800
Swimming Pools - General - Total Family Pool Complex Exterior Painting - Pavilion Metal Roof - Pavilion	2006 2006	22-23 35-36	10 30	5 0	0 13	3,400 Square Feet 3,214 Square Feet	2.00 16.00	\$248,990 6,800 51,424
Swimming Pools - General - Total Family Pool Complex Exterior Painting - Pavilion Metal Roof - Pavilion Pool Resurfacing	2006 2006 2014	22-23 35-36 28-29	10 30 15	5 0 0	0 13 6	3,400 Square Feet 3,214 Square Feet 9,000 Square Feet	2.00 16.00 14.00	\$248,990 6,800 51,424 126,000

			edi.		o Silv	%		
	Ough Ser	يې پروف	gent Jest	\$ ***	Start of	ggin .gs	.≽. ≿	Children Cost
Description	ನ್ಯೂ ಜ್ಯಾ	र्क्ट्रय	*** 5°	A.O.	, 5 ₀	Jäts Jäts	Jät Cost	Car Car
Lap Pool Complex								
Exterior Painting - Pavilion	2017	26-27	10	0	4	1 Lump Sum	3,200.00	3,200
Exterior Painting - Restroom Pavilion	2011	22-23	10	0	0	1,800 Square Feet	1.25	2,250
Lane Divider Reel	2006	30-31	20	5	8	1 Each	1,940.00	1,940
Lane Dividers	2006	22-23	10	6	0	8 Lanes	520.00	4,160
Light Poles	2011	35-36	25	0	13	6 EA	3,000.00	18,000
Metal Roof - Pavilion	2011	45-46	35	0	23	1,620 Square Feet	16.00	25,920
Metal Roof - Restroom Pavilion	2011	45-46	35	0	23	1,660 Square Feet	16.00	26,560
Pool Heater Allowance	2018	27-28	10	0	52	,070,000 BTU	0.02	41,400
Pool Lift	2006	23-24	15	3	1	1 Each	3,200.00	3,200
Pool Resurfacing	2011	22-23	12	0	0	6,146 Square Feet	14.00	86,044
Pool Solar Blanket	2011	22-23	8	0	0	4,200 Square Feet	1.20	5,040
Pool Solar Blanket Reel	2011	26-27	16	0	4	1 Each	1,200.00	1,200
Refurbishment Allowance - Lap Pool Restro	2006	25-26	20	0	3	2 Each	8,000.00	16,000
Starting Platforms	2006	30-31	25	0	8	6 Each	2,700.00	16,200
Water Coolers	2006	22-23	12	0	0	2 Each	1,100.00	2,200
Lap Pool Complex - Total								\$253,314
Culash Dool								
Splash Pool	2006	20.21	25	0	0	1.1. 0	40,000,00	40,000
Pool Play Equipment Allowance	2006	30-31	25	0	8	1 Lump Sum	40,000.00	40,000
Pool Resurfacing	2014	28-29	15	0	6	1,870 Square Feet	12.00	22,440
Splash Pool - Total								\$62,440
Playground - Clubhouse								
Bipod Swings - 2 Bay	2017	31-32	15	0	9	1 Each	3,200.00	3,200
Cresent Climber	2017	34-35	18	0	12	1 Each	2,100.00	2,100
Park Benches	2017	30-31	14	0	8	10 Each	1,300.00	13,000
Picnic Tables	2006	27-28	20	2	5	4 Each	2,100.00	8,400
Plastic Play Surface Border	2017	36-37	20	0	14	490 Linear Feet	21.00	10,290
Play Equipment Allowance	2017	29-30	12	0	7	1 Lump Sum	45,000.00	45,000
Speedy Spinner	2017	28-29	12	0	6	1 Each	5,000.00	5,000
Spring Riders	2017	31-32	15	0	9	2 Each	1,600.00	3,200
Wood Park Benches	2017	36-37	20	0	14	1 Lump Sum	1,800.00	1,800
Wood Play Equipment	2017	29-30	12	0	7	1 Lump Sum	15,000.00	15,000
Playground - Clubhouse - Total						•		\$106,990
Dlavaround Doorston Doub								
Playground - Deerview Park	2006	22.22	1.5	0	0	1 🖸 1	2 200 00	2 200
Bi-Pod Swing Set	2006	22-23	15	0	0	1 Each	3,200.00	3,200
Cresent Climber	2006	23-24	18	0	1	1 Each	2,800.00	2,800
Gazebo Roof	2006	35-36	30	0	13	600 Square Feet	8.00	4,800
Park Benches	2006	22-23	16	0	0	1 Each	1,200.00	1,200
Picnic Tables	2006	22-23	16	0	0	2 Each	1,300.00	2,600
Plastic Play Surface Border	2006	25-26	20	0	3	291 Linear Feet	21.00	6,111
Play Equipment Allowance	2006	22-23	15	0	0	1 Lump Sum	30,000.00	30,000
Spring Rider	2006	22-23	15	0	0	1 Each	1,600.00	1,600

			egit		×	60		
	₽.	ළ දුර්	, Se	>	extrev is	in the state of th		
Description	Spirit in	50 76	gent Jestî	V V	& Selling	Silis	Jit ost	CHI CO'S
Playground - Deerview Park continued								
Vinyl Privacy Fence	2006	35-36	30	0	13	200 Linear Feet	31.00	6,200
Vinyl Ranch Fence	2006	30-31	25	0	8	462 Linear Feet	24.00	_11,088
Playground - Deerview Park - Total								\$69,599
Playground - Hamilton Glen Park								
Bi-Pod Swing Set	2006	22-23	15	0	0	1 Each	3,200.00	3,200
Gazebo Roof	2006	35-36	30	0	13	600 SF	8.00	4,800
Park Bench	2006	22-23	16	0	0	1 Each	1,300.00	1,300
Picnic Tables	2006	22-23	16	0	0	2 Each	1,300.00	2,600
Plastic Play Surface Border	2006	25-26	20	0	3	120 Linear Feet	21.00	2,520
Play Equipment Allowance	2006	22-23	15	0	0	1 Lump Sum	30,000.00	30,000
Vinyl Privacy Fence	2006	35-36	30	0	13	237 Linear Feet	31.00	7,347
Playground - Hamilton Glen Park - Total								\$51,767
Playgrounds - Whitfield Park								
Bi-Pod Swing Set	2006	22-23	15	0	0	1 Each	3,200.00	3,200
Gazebo Roof	2006	35-36	30	0	13	600 Square Feet	8.00	4,800
Park Bench	2006	22-23	16	0	0	1 Each	1,200.00	1,200
Picnic Tables	2006	22-23	16	0	0	2 Each	1,300.00	2,600
Plastic Play Surface Border	2006	25-26	20	0	3	260 Linear Feet	21.00	5,460
Play Equipment Allowance	2006	22-23	15	0	0	1 Lump Sum	30,000.00	30,000
Vinyl Privacy Fence	2006	35-36	30	0	13	426 Linear Feet	31.00	13,206
Vinyl Ranch Fence	2006	35-36	30	0	13	495 Linear Feet	24.00	11,880
Playgrounds - Whitfield Park - Total								\$72,346
Maintenance Shop & Equipment								
All Terain Vehicle	2014	28-29	15	0	6	1 Lump Sum	10,000.00	10,000
Exterior Painting	2011	22-23	10	0	0	3,300 Square Feet	2.00	6,600
Golf Cart	2006	22-23	15	0	0	3 Each	5,000.00	15,000
Jon Boat & Motor Allowance	2006	25-26	20	0	3	1 Each	6,500.00	6,500
Metal Roof	2011	40-41	30	0	18	3,056 Square Feet	16.00	48,896
Maintenance Shop & Equipment - Total								\$86,996
Operating Expense								
Flooring - Office	11	nfunded						
Furniture - Second Floor Clubhouse		njunaea nfunded						
Interior Painting - Office		nfunded nfunded						
Office Equipment & Furniture Allowance		nfunded						
Parking Lot Seal Coat		nfunded						
Steel Trash Cans		nfunded						
Wood Mulch - Play Areas		nfunded						•
Operating Expense Total	0	,						

Operating Expense - Total

इंट टॉडॉ

Description

Components Not Included

Clock Tower Clock
Fabric Shade Awnings - Tennis Curts
Components Not Included - Total

Unfunded Unfunded

Total Asset Summary \$3,193,245

Middle Village CDD Component Detail Index

Site Components - General1062Decorative Fountain Refurbishment Allowance22-235-151020Irrigation System Repair Allowance22-235-151025Well 4" Pump - Tennis Courts22-235-151024Well 6" Pump - Oakleaf Plantation Parkway22-235-161026Well 6" Pump - Plantation Oaks Blvd. West22-235-161021Wood Boardwalk Replacement46-475-16
1062Decorative Fountain Refurbishment Allowance22-235-151020Irrigation System Repair Allowance22-235-151025Well 4" Pump - Tennis Courts22-235-151024Well 6" Pump - Oakleaf Plantation Parkway22-235-161026Well 6" Pump - Plantation Oaks Blvd. West22-235-16
1020Irrigation System Repair Allowance22-235-151025Well 4" Pump - Tennis Courts22-235-151024Well 6" Pump - Oakleaf Plantation Parkway22-235-161026Well 6" Pump - Plantation Oaks Blvd. West22-235-16
1025Well 4" Pump - Tennis Courts22-235-151024Well 6" Pump - Oakleaf Plantation Parkway22-235-161026Well 6" Pump - Plantation Oaks Blvd. West22-235-16
1024Well 6" Pump - Oakleaf Plantation Parkway22-235-161026Well 6" Pump - Plantation Oaks Blvd. West22-235-16
1026 Well 6" Pump - Plantation Oaks Blvd. West 22-23 5-16
Site Components - Monuments
1208 Brick Tuck Point & Seal - Bell Tower 25-26 5-18
1195 Brick Tuck Point & Seal - Clock Tower 25-26 5-18
1209 Exterior Paint - Bell Tower 22-23 5-18
1196 Exterior Paint - Clock Tower 22-23 5-19
1207 Metal Roof - Bell Tower 40-41 5-20
1194 Metal Roof - Clock Tower 40-41 5-20
Site Components - Signage
1071 Refurbishment Allowance - Amenity Monument Sign 29-30 5-21
1072 Refurbishment Allowance - Deerview Lane entry 29-30 5-21
1074 Refurbishment Allowance - Hamilton Glen Entry 29-30 5-21
1073 Refurbishment Allowance - Whitfield Entry 29-30 5-22
Site Components - Fencing
1238 Aluminum Fence 8 Ft - Amenity 46-47 5-23
1239 Chain Link Fence - Maintence Shed 42-43 5-23
1004 Dumpster Enclosure Gates 22-23 5-24
1204 Vinyl Fencing - Deerview 35-36 5-24
1006 Vinyl Fencing - Hamilton Glen 35-36 5-25
1205 Vinyl Fencing - Whitfield 35-36 5-25
Site Components - Parking Lots
1241 Concrete Pavers - Parking Lot 35-36 5-26
1027 Light Poles 30-31 5-26
1126 Light Poles 30-31 5-26
1125 Parking Lot Mill & Resurface 27-28 5-27
Clubhouse - General
1003 Access Control Panel 28-29 5-28

Middle Village CDD Component Detail Index

Asset I	DDescription	Replacement	Page
Clubho	ouse - General Continued		
1091	Exterior Painting - Clubhouse	25-26	5-28
1206	Guard Rail	30-31	5-28
1114	Kitchen Cabinet & Equipment - Snack Bar	25-26	5-29
1075	Monument Stair Railings	40-41	5-30
1232	Painting - Guard Rails	22-23	5-30
1227	Painting - Monument Stair Rails	22-23	5-31
1002	Security Camera System Allowance	22-23	5-31
1103	Water Coolers	30-31	5-31
1104	Water Heater	22-23	5-32
Clubh	ouse - Roofing		
1108	Asphalt Shingles	23-24	5-33
1109	Standing Seam Metal Roof	40-41	5-33
C1 11	E' C /		
	ouse - Fitness Center	22.22	5 24
1086	Carpet Tile	22-23	5-34
1115	Fitness Equip Partial Allowance	22-23	5-34
1094	<u>e</u>	22-23	5-34
1121	Wall Mounted Televisions	23-24	5-35
Clubh	ouse - Locker Rooms		
1234	Refurbishment Allowance - Locker Rooms	25-26	5-36
	ouse - Second Floor Components		
1100	Cabinets & Laminate Top - Kitchen	30-31	5-37
1090	Floor Tile - Kitchen	30-31	5-37
1123	Folding Tables & Chairs Allowance	22-23	5-37
1117	Freezer	32-33	5-38
1244	Ice Machine	25-26	5-38
1092	Interior Wall Painting	22-23	5-39
1116	Microwave - Kitchen	25-26	5-39
1120	Range - Kitchen	25-26	5-40
1124	Refrigerator - Kitchen	35-36	5-40
1235	Refurbishment Allowance - Restooms	28-29	5-41
1084	Vinyl Flooring	37-38	5-41
1077	Window Treatment Allowance	25-26	5-42

Middle Village CDD Component Detail Index

Asset I	DDescription	Replacement	Page
Clubho	ouse - Mechanical Systems		
1030	HVAC Unit 1	31-32	5-43
1029	HVAC Unit 2	31-32	5-43
1031	HVAC Unit 3	33-34	5-43
Clubho	ouse - Elevator		
1033	Elevator Cab Refurbishment	30-31	5-44
1034	Elevator Equipment Modernization	40-41	5-44
Lake P	avilion		
1217	Composit Deck & Rails	41-42	5-45
1193	Exterior Painting - Pavilion	22-23	5-45
1191	Metal Roof - Pavilion	40-41	5-46
1218	Wood Bulkhead	33-34	5-46
1192	Wood Repair - Pavilion	30-31	5-47
Lawn 1	Pavilions		
1081	Asphalt Shingles	25-26	5-48
1082	Exterior Painting	26-27	5-48
Sports	Pavilion		
1068	Exterior Painting	22-23	5-49
1066	Metal Roof	40-41	5-49
1067	Restroom Refurbishment	25-26	5-50
1069	Water Cooler	22-23	5-50
Ball Fi	elds		
1065	Chain Link Back Stops	27-28	5-51
1070	Chain Link Dugouts & Roof	27-28	5-51
1063	Chain Link Fencing 4 Ft	27-28	5-51
1064	Chain Link Fencing 6 Ft	27-28	5-52
Basket	ball Courts		
1045	Basketball Court Resurfacing	22-23	5-53
1046	Basketball Pole & Backboard	22-23	5-53
1048	Chain Link Fencing	24-25	5-54
1047	Light Poles	30-31	5-54

Asset I	DDescription	Replacement	Page
Tennis	Complex		
1043	Asphalt Shingles - Maintenance Building	25-26	5-55
1037	Exterior Painting - Maintenance Building	22-23	5-55
1041	Exterior Painting - Pavilion	22-23	5-56
1036	HVAC Unit - Tennis Office	22-23	5-56
1040	Metal Roof - Pavilion	40-41	5-56
1236	Refurbishment Allowance - Restrooms	25-26	5-57
1044	Water Coolers	35-36	5-58
1219	Wood Pergola - Pavilion	27-28	5-58
Tennis	Courts		
1162	Aluminium Fence - Patio	48-49	5-59
1163		33-34	5-59
1155	Chain Link Fencing - 10 Ft	42-43	5-59
1157	Chain Link Fencing - 4 Ft	29-30	5-60
1154	Light Poles	30-31	5-60
1159	Shade Pavilions	25-26	5-61
1153	Tennis Court Replenishment Allowance	22-23	5-61
1156	Wind Screens	28-29	5-62
1158	Wood Bulkheads	35-36	5-62
Swimn	ning Pools - General		
1010	Aluminium Fencing	35-36	5-63
1018	Asphalt Shingles - Sidewalk Pavilion	25-26	5-63
1243	Concrete Pavers - Pool Decks	35-36	5-64
1230	Exterior Painting - Pool Slide Tower	28-29	5-64
1015	HVAC Unit - Pool Office	22-23	5-65
1170	Lifeguard Chairs	22-23	5-65
1008	Light Poles	30-31	5-65
1017	Metal Roof - Pool Slide Building	35-36	5-66
1007	Pool Furniture Annual Allowance	22-23	5-66
1009	Pool Pumps & Equipment Annual Allowance	22-23	5-67
1013	Pool Shade Structures	38-39	5-67
1016	Pool Slide Railing	30-31	5-68
1014	Pool Slide Refurbishment	31-32	5-68
1019	Vinyl Fence - Pool Equipment Yard	35-36	5-68
Family	Pool Complex		
1164	Exterior Painting - Pavilion	22-23	5-69

Asset ID Description		Replacement	Page	
Family Pool Complex Continued				
1168	Metal Roof - Pavilion	35-36	5-69	
1166	Pool Resurfacing	28-29	5-70	
1237	Refurbishment Allowance - Restrooms	25-26	5-70	
1165	Wood Pergola	30-31	5-71	
Lan Pa	ool Complex			
1210	Exterior Painting - Pavilion	26-27	5-72	
1180	Exterior Painting - Restroom Pavilion	22-23	5-72	
1211	Lane Divider Reel	30-31	5-73	
1188	Lane Dividers	22-23	5-74	
1178	Light Poles	35-36	5-74	
1181	Metal Roof - Pavilion	45-46	5-75	
1179	Metal Roof - Restroom Pavilion	45-46	5-75	
1189	Pool Heater Allowance	27-28	5-76	
1187	Pool Lift	23-24	5-76	
1175	Pool Resurfacing	22-23	5-77	
1182	Pool Solar Blanket	22-23	5-77	
1212	Pool Solar Blanket Reel	26-27	5-78	
1242	Refurbishment Allowance - Lap Pool Restrooms	25-26	5-78	
1233	Starting Platforms	30-31	5-79	
1216	Water Coolers	22-23	5-79	
Splash	Pool			
1213	Pool Play Equipment Allowance	30-31	5-80	
1190	Pool Resurfacing	28-29	5-80	
Playgr	ound - Clubhouse			
1052	Bipod Swings - 2 Bay	31-32	5-81	
1054	Cresent Climber	34-35	5-81	
1058	Park Benches	30-31	5-82	
1059	Picnic Tables	27-28	5-82	
1057	Plastic Play Surface Border	36-37	5-82	
1049	Play Equipment Allowance	29-30	5-83	
1051	Speedy Spinner	28-29	5-83	
1050	Spring Riders	31-32	5-84	
1053	Wood Park Benches	36-37	5-84	
1055	Wood Play Equipment	29-30	5-85	

Asset I	DDescription	Replacement	Page
Playgr	ound - Deerview Park		
1136	Bi-Pod Swing Set	22-23	5-86
1249	Cresent Climber	23-24	5-86
1131	Gazebo Roof	35-36	5-87
1132	Park Benches	22-23	5-87
1225	Picnic Tables	22-23	5-88
1135	Plastic Play Surface Border	25-26	5-88
1130	Play Equipment Allowance	22-23	5-89
1247	Spring Rider	22-23	5-89
1224	Vinyl Privacy Fence	35-36	5-90
1129	Vinyl Ranch Fence	30-31	5-90
Plavgr	ound - Hamilton Glen Park		
1141	Bi-Pod Swing Set	22-23	5-91
1137	Gazebo Roof	35-36	5-91
1142	Park Bench	22-23	5-92
1143	Picnic Tables	22-23	5-92
1140	Plastic Play Surface Border	25-26	5-93
1138	Play Equipment Allowance	22-23	5-93
1144	Vinyl Privacy Fence	35-36	5-94
Plavgr	ounds - Whitfield Park		
1152	Bi-Pod Swing Set	22-23	5-95
1147	Gazebo Roof	35-36	5-95
1150	Park Bench	22-23	5-95
1148	Picnic Tables	22-23	5-96
1151	Plastic Play Surface Border	25-26	5-96
1146	Play Equipment Allowance	22-23	5-97
1222	Vinyl Privacy Fence	35-36	5-97
1145	Vinyl Ranch Fence	35-36	5-98
Maint	enance Shop & Equipment		
1113	All Terain Vehicle	28-29	5-99
1080	Exterior Painting	22-23	5-99
1111	Golf Cart	22-23	5-99
1112	Jon Boat & Motor Allowance	25-26	5-99
1079	Metal Roof	40-41	5-100

Asset I	DDescription	Replacement	Page
Operat	ing Expense		
1083	Flooring - Office	22-23	5-101
1119	Furniture - Second Floor Clubhouse	22-23	5-101
1093	Interior Painting - Office	22-23	5-101
1118	Office Equipment & Furniture Allowance	22-23	5-101
1127	Parking Lot Seal Coat	22-23	5-102
1149	Steel Trash Cans	22-23	5-102
1056	Wood Mulch - Play Areas	22-23	5-102
Compo	onents Not Included		
1245	Clock Tower Clock	22-23	5-103
1160	Fabric Shade Awnings - Tennis Curts	27-28	5-103
	Total Funded Assets	172	
	Total Unfunded Assets	_9	
	Total Assets	181	

Decorative Fountain Refurbishment Allowance - 2022

Asset ID 1062 Asset Actual Cost \$3,000.00

Percent Replacement 100%

Site Components - General Future Cost \$3,000.00

Placed in Service
Useful Life

Replacement Year
Remaining Life

June 2006

22-23

0



Irrigation System Repair Allowance - 2022

1 Lump Sum @ \$3,000.00 Asset ID 1020 **Asset Actual Cost** \$3,000.00 Percent Replacement 100% Site Components - General **Future Cost** \$3,000.00 Placed in Service June 2012 Useful Life 5 Replacement Year 22-23

0

Well 4" Pump - Tennis Courts - 2022

Remaining Life

Asset ID 1025 Asset Actual Cost \$4,500.00

Percent Replacement 100%

Site Components - General Future Cost \$4,500.00

Placed in Service
Useful Life
12
Replacement Year
Remaining Life
June 2006
22-23
0

Community Advisors Page 5-15 May 10, 2022

Well 6" Pump - Oakleaf Plantation Parkway - 2022

		1 Each	@ \$6,200.00
Asset ID	1024	Asset Actual Cost	\$6,200.00
		Percent Replacement	100%
Site	Components - General	Future Cost	\$6,200.00
Placed in Service	June 2006		
Useful Life	12		
Adjustment	2		
Replacement Year	22-23		
Remaining Life	0		

Well 6" Pump - Plantation Oaks Blvd. West - 2022

		1 Lump Sum	@ \$6,200.00
Asset ID	1026	Asset Actual Cost	\$6,200.00
		Percent Replacement	100%
Site	Components - General	Future Cost	\$6,200.00
Placed in Service	June 2006		
Useful Life	12		
Adjustment	3		
Replacement Year	22-23		
Remaining Life	0		

Wood Boardwalk Replacement - 2046

		3,479 Square Feet	@ \$41.00
Asset ID	1021	Asset Actual Cost	\$142,639.00
		Percent Replacement	100%
Site Components - General		Future Cost	\$307,148.58
Placed in Service	June 2022		
Useful Life	25		
Replacement Year	46-47		
Remaining Life	24		

Wood Boardwalk Replacement continued...



Brick Tuck Point & Seal - Bell Tower - 2025

Asset ID	1208	3,000 Square Feet Asset Actual Cost Percent Replacement	@ \$6.20 \$18,600.00 100%
Site Components - Monuments		Future Cost	\$21,529.87
Placed in Service	June 2006		
Useful Life	20		
Replacement Year	25-26		
Remaining Life	3		



Brick Tuck Point & Seal - Clock Tower - 2025

Asset ID	1195	3,400 Square Feet Asset Actual Cost Percent Replacement	@ \$6.20 \$21,080.00 100%
Site Components - Monuments		Future Cost	\$24,400.52
Placed in Service	June 2006		
Useful Life	20		
Replacement Year	25-26		
Remaining Life	3		

Exterior Paint - Bell Tower - 2022

tterior Paint - Bell Towe	er - 2022	1,200 Square Feet	@ \$5.00
Asset ID	1209	Asset Actual Cost	\$6,000.00
		Percent Replacement	100%
Site Componer	nts - Monuments	Future Cost	\$6,000.00
Placed in Service	June 2006		
Useful Life	12		
Replacement Year	22-23		
Remaining Life	0		

Exterior Paint - Bell Tower continued...



Exterior Paint - Clock Tower - 2022

Replacement Year

Remaining Life

		1,200 Square Feet	@ \$5.00
Asset ID	1196	Asset Actual Cost	\$6,000.00
		Percent Replacement	100%
Site Components - Monuments		Future Cost	\$6,000.00
Placed in Service	June 2006		
Useful Life	12		



22-23

0

Metal Roof - Bell Tower - 2040

Asset ID 1207

429 Square Feet @ \$19.00 Asset Actual Cost \$8,151.00 Percent Replacement 100% Future Cost \$14,699.34

Site Components - Monuments Placed in Service June 2006

Useful Life 35
Replacement Year 40-41
Remaining Life 18



Metal Roof - Clock Tower - 2040

Asset ID 1194

429 Square Feet @ \$19.00 Asset Actual Cost \$8,151.00 Percent Replacement 100% Future Cost \$14,699.34

Site Components - Monuments
Placed in Service
Useful Life
35
Replacement Year
Remaining Life
35
18



Clock mechanism replacement not included

Refurbishment Allowance - Amenity Monument Sign - 2029

		1 Lump Sum	@ \$3,000.00
Asset ID	1071	Asset Actual Cost	\$3,000.00
		Percent Replacement	100%
Site	Components - Signage	Future Cost	\$3,908.40
Placed in Service	June 2020		
Useful Life	10		
Replacement Year	29-30		
Remaining Life	7		

Refurbishment Allowance - Deerview Lane entry - 2029

		1 Lump Sum	@ \$3,000.00
Asset ID	1072	Asset Actual Cost	\$3,000.00
		Percent Replacement	100%
Site	Components - Signage	Future Cost	\$3,908.40
Placed in Service	June 2020		
Useful Life	10		
Replacement Year	29-30		
Remaining Life	7		

Refurbishment Allowance - Hamilton Glen Entry - 2029

		1 Lump Sum	@ \$3,000.00
Asset ID	1074	Asset Actual Cost	\$3,000.00
		Percent Replacement	100%
Site	Components - Signage	Future Cost	\$3,908.40
Placed in Service	June 2020		
Useful Life	10		
Replacement Year	29-30		
Remaining Life	7		

Refurbishment Allowance - Hamilton Glen Entry continued...



Refurbishment Allowance - Whitfield Entry - 2029

		1 Lump Sum	@ \$3,000.00
Asset ID	1073	Asset Actual Cost	\$3,000.00
		Percent Replacement	100%
Site	Components - Signage	Future Cost	\$3,908.40
Placed in Service	June 2020		
Useful Life	10		
Replacement Year	29-30		
Remaining Life	7		



Aluminum Fence 8 Ft - Amenity - 2046

Asset ID 1238 Asset Actual Cost \$84,864.00
Percent Replacement 100%
Site Components - Fencing Future Cost \$182,740.04

Placed in Service May 2022
Useful Life 25
Replacement Year 46-47
Remaining Life 24



Chain Link Fence - Maintence Shed - 2042

Asset ID 1239 Asset Actual Cost \$8,680.00
Percent Replacement 100%
Site Components - Fencing Future Cost \$16,606.61

Placed in Service
Useful Life

Replacement Year
Remaining Life

June 2019
42-43
42-43



Community Advisors Page 5-23 May 10, 2022

Dumpster Enclosure Gates - 2022

Asset ID 1004

4 EA @ \$1,600.00
Asset Actual Cost \$6,400.00
Percent Replacement 100%
Future Cost \$6,400.00

Site Components - Fencing
Placed in Service June 2006
Liceful Life 20

Useful Life 20
Adjustment -3
Replacement Year 22-23
Remaining Life 0



Vinyl Fencing - Deerview - 2035

Asset ID 1204

7,400 Linear Feet @ \$31.00
Asset Actual Cost \$229,400.00
Percent Replacement 100%
Future Cost \$356,856.95

Site Components - Fencing
Placed in Service June 2006
Useful Life 30
Replacement Year 35-36
Remaining Life 13



13

Vinyl Fencing - Hamilton Glen - 2035

		2,426 Linear Feet	@ \$31.00
Asset ID	1006	Asset Actual Cost	\$75,206.00
		Percent Replacement	100%
Site C	Components - Fencing	Future Cost	\$116,991.21
Placed in Service	June 2006		
Useful Life	30		
Replacement Year	35-36		

.

Vinyl Fencing - Whitfield - 2035

Remaining Life

cing - Whitfield - 2035		3,800 Linear Feet	@ \$31.00
Asset ID	1205	Asset Actual Cost	\$117,800.00
		Percent Replacement	100%
Site Components - Fencing		Future Cost	\$183,250.87

Placed in Service
Useful Life
Replacement Year
Remaining Life
June 2006
30
35-36
Remaining Life
13

Concrete Pavers - Parking Lot - 2035

Asset ID	1241	800 Square Feet Asset Actual Cost Percent Replacement	@ \$8.15 \$6,520.00 100%
Site Compone	ents - Parking Lots	Future Cost	\$10,142.58
Placed in Service	June 2006		
Useful Life	30		
Replacement Year	35-36		
Remaining Life	13		



T : 1 . D 1 2000			
Light Poles - 2030		8 Each	@ \$1,400.00
Asset ID	1027	Asset Actual Cost	\$11,200.00
		Percent Replacement	100%
Site Compo	onents - Parking Lots	Future Cost	\$15,029.09
Placed in Service	June 2006		
Useful Life	25		
Replacement Year	30-31		
Remaining Life	8		

Light Poles - 2030		14 EA	@ \$1,800.00
Asset ID	1126	Asset Actual Cost	\$25,200.00
		Percent Replacement	100%
Site Components	- Parking Lots	Future Cost	\$33,815.45
Placed in Service	June 2006		
Useful Life	25		
Replacement Year	30-31		
Remaining Life	8		

Light Poles continued...



Parking Lot Mill & Resurface - 2027

Asset ID	1125	12,724 Square Yards Asset Actual Cost Percent Replacement	@ \$17.10 \$217,580.40 100%
Site Componer	nts - Parking Lots	Future Cost	\$267,191.55
Placed in Service	June 2006		
Useful Life	20		
Adjustment	2		
Replacement Year	27-28		
Remaining Life	5		
_			

A	α	D 1	2020
Access	Control	Panel	- 2028

@ \$3,800.00 Asset ID 1003 **Asset Actual Cost** \$3,800.00 Percent Replacement 100% Clubhouse - General **Future Cost** \$4,806.44

1 Each

Placed in Service June 2014 Useful Life 15 Replacement Year 28-29 Remaining Life 6

Exterior Painting - Clubhouse - 2025

14,640 Square Feet @ \$2.80 Asset ID 1091 Asset Actual Cost \$40,992.00 Percent Replacement 100% Clubhouse - General **Future Cost** \$47,449.06

Placed in Service June 2006 Useful Life 10 Adjustment 10 Replacement Year 25-26 Remaining Life 3



Guard Rail - 2030

1206 Asset Actual Cost \$22,940.00 Asset ID

310 Linear Feet

@ \$74.00

Percent Replacement 100% Clubhouse - General **Future Cost** \$30,782.79 Placed in Service June 2006

Useful Life 25 Replacement Year 30-31 Remaining Life 8

Guard Rail continued...



Kitchen Cabinet & Equipment - Snack Bar - 2025

Asset ID 1114 Asset Actual Cost \$8,400.00
Percent Replacement 100%
Clubhouse - General Future Cost \$9,723.17

Placed in Service
Useful Life
Replacement Year
Remaining Life
Useful Life
20
25-26
Remaining Life
3



- 1 Refrigerator
- 1 Freeezer
- I Microwave
- 1Three Compartment sink
- 1 Bar sink
- Cabinets and Tops

Monument Stair Railings - 2040

Asset ID 1075

436 Linear Feet @ \$82.00 Asset Actual Cost \$35,752.00 Percent Replacement 100% Future Cost \$64,474.39

Clubhouse - General
Placed in Service
Useful Life
Steplacement Year
Remaining Life
Clubhouse - General
June 2006
40-41
40-41



Painting - Guard Rails - 2022

Asset ID 1232

340 Linear Feet @ \$9.30 Asset Actual Cost \$3,162.00 Percent Replacement 100% Future Cost \$3,162.00

Placed in Service
Useful Life
Useplacement Year
Remaining Life

Clubhouse - General
June 2012
2012
22-23



Painting - Monument Stair Rails - 2022

		436 Linear Feet	@ \$9.30
Asset ID	1227	Asset Actual Cost	\$4,054.80
		Percent Replacement	100%
	Clubhouse - General	Future Cost	\$4,054.80

Placed in Service	June 2006
Useful Life	10
Adjustment	1
Replacement Year	22-23
Remaining Life	0



Security Camera System Allowance - 2022

		1 Lump Sum	@ \$15,000.00
Asset ID	1002	Asset Actual Cost	\$15,000.00
		Percent Replacement	100%
	Clubhouse - General	Future Cost	\$15,000.00
Placed in Service	June 2010		
Useful Life	10		
Replacement Year	22-23		
Remaining Life	0		

Asset ID	1103	Asset Actual Cost	\$6,300.00
		Percent Replacement	100%
	Clubhouse - General	Future Cost	\$8,453.86

Placed in Service June 2019
Useful Life 12
Replacement Year 30-31
Remaining Life 8

Community Advisors Page 5-31 May 10, 2022

Water Coolers continued...



Water Heater - 2022

Asset ID 1104 Asset Actual Cost

@ \$36.00

\$3,060.00

85 Gallon

Percent Replacement 100%
Clubhouse - General Future Cost \$3,060.00
Placed in Service Useful Life 12

Replacement Year 22-23
Remaining Life 0

Asphalt Shingles - 2023

Asset ID 1108

139 Squares @ \$440.00 Asset Actual Cost \$61,160.00 Percent Replacement 100% Future Cost \$64,829.60

Clubhouse - Roofing June 2006

Placed in Service June 2006
Useful Life 20
Adjustment -2
Replacement Year 23-24
Remaining Life 1



Standing Seam Metal Roof - 2040

Asset ID 1109

Placed in Service
Useful Life
Replacement Year
Remaining Life

Clubhouse - Roofing
June 2006
40-41
40-41



$\boldsymbol{\alpha}$		D'1	2022
Car	net	I He	- 2022
$-\alpha$		1110	

 - 2022
 165 SY
 @ \$38.00

 Asset ID
 1086
 Asset Actual Cost
 \$6,270.00

 Percent Replacement
 100%

 Clubhouse - Fitness Center
 Future Cost
 \$6,270.00

Placed in Service June 2013
Useful Life 10
Replacement Year 22-23
Remaining Life 0



Fitness Equip Partial Allowance - 2022

Asset ID 1115 Asset Actual Cost \$3,000.00
Percent Replacement 100%
Clubhouse - Fitness Center Future Cost \$3,000.00
Placed in Service June 2014

Useful Life 1
Replacement Year 22-23
Remaining Life 0

Interior Painting - Fitness - 2022

Asset ID 1094 1,152 Square Feet @ \$2.00
Asset ID 1094 Asset Actual Cost \$2,304.00
Percent Replacement 100%
Clubhouse - Fitness Center Future Cost \$2,304.00

Placed in Service
Useful Life
Replacement Year
Remaining Life
June 2013
22-23
0

Community Advisors Page 5-34 May 10, 2022

Wall Mounted Televisions	s - 2023	3 Each	@ \$800.00
Asset ID	1121	Asset Actual Cost	\$2,400.00
		Percent Replacement	100%
Clubhouse	- Fitness Center	Future Cost	\$2,544.00
Placed in Service	June 2014		
Useful Life	10		
Replacement Year	23-24		
Remaining Life	1		

Refurbishment Allowance - Locker Rooms - 2025

Asset ID	1234	1,400 Square Feet Asset Actual Cost Percent Replacement	@ \$48.00 \$67,200.00 100%
Clubho	use - Locker Rooms	Future Cost	\$77,785.34
Placed in Service	June 2006		
Useful Life	20		
Replacement Year	25-26		
Remaining Life	3		



Cabinets & Laminate Top - Kitchen - 2030

		18 Linear Feet	@ \$185.00
Asset ID	1100	Asset Actual Cost	\$3,330.00
		Percent Replacement	100%
Clubhouse - Second Flo	oor Components	Future Cost	\$4,468.47
Placed in Service	June 2006		
Useful Life	20		
Adjustment	5		
Replacement Year	30-31		
Remaining Life	8		



Floor Tile - Kitchen - 2030		200 Square Feet	@ \$14.00
Asset ID	1090	Asset Actual Cost	\$2,800.00
		Percent Replacement	100%
Clubhouse - Second Floor	Components	Future Cost	\$3,757.27
Placed in Service	June 2006		
Useful Life	20		
Adjustment	5		
Replacement Year	30-31		
Remaining Life	8		

Folding Tables & Chairs	Allowance - 2022	1 LS	@ \$3,000.00
Asset ID	1123	Asset Actual Cost	\$3,000.00
		Percent Replacement	100%
Clubhouse - Second F.	loor Components	Future Cost	\$3,000.00
Placed in Service	June 2006		
Useful Life	15		
Replacement Year	22-23		
Remaining Life	0		

Freezer - 2032

Asset ID 1117

1 Each @ \$3,800.00
Asset Actual Cost \$3,800.00
Percent Replacement 100%
Future Cost \$5,409.69

Clubhouse - Second Floor Components
Placed in Service June 2021
Useful Life 12
Replacement Year 32-33
Remaining Life 10



Ice Machine - 2025

Asset ID 1244

Clubhouse - Second Floor Components
Placed in Service
Useful Life
20
Replacement Year
Remaining Life
3



Interior Wall Painting - 2022

Asset ID 1092

6,300 Square Feet @ \$1.10 Asset Actual Cost \$6,930.00 Percent Replacement 100% Future Cost \$6,930.00

Clubhouse - Second Floor Components
Placed in Service June 2006
Useful Life 5
Adjustment 12
Replacement Year 22-23
Remaining Life 0



Microwave - Kitchen - 2025

Asset ID 1116

1 Each @ \$600.00 Asset Actual Cost \$600.00 Percent Replacement 100% Future Cost \$694.51

Clubhouse - Second Floor Components
Placed in Service June 2016
Useful Life 10
Replacement Year 25-26
Remaining Life 3



Community Advisors Page 5-39 May 10, 2022

Range - Kitchen - 2025

1 Each	@ \$1,600.00		
Asset ID	1120	Asset Actual Cost	\$1,600.00
Percent Replacement	100%		
Clubhouse - Second Floor Components	Future Cost	\$1,852.03	

Placed in Service June 2006
Useful Life 12
Adjustment 8
Replacement Year 25-26
Remaining Life 3



Refrigerator - Kitchen - 2035

Asset ID 1124 Asset Actual Cost \$3,500.

Clubhouse - Second Floor Components
Placed in Service June 2021
Useful Life 15
Replacement Year 35-36
Remaining Life 13



Community Advisors Page 5-40 May 10, 2022

Refurbishment Allowance - Restooms - 2028

		460 Square Feet	@ \$64.00
Asset ID	1235	Asset Actual Cost	\$29,440.00
		Percent Replacement	100%
Clubhouse - Secon	nd Floor Components	Future Cost	\$37,237.28
Placed in Service	June 2006		
Useful Life	20		
Adjustment	3		
Replacement Year	28-29		
Remaining Life	6		



Vinyl Flooring - 2037

Asset ID 1084

Clubhouse - Second Floor Components
Placed in Service June 2018
Useful Life 20
Replacement Year 37-38
Remaining Life 15



Community Advisors Page 5-41 May 10, 2022

Window Treatment Allowance - 2025

Asset ID 1077

16 Each @ \$400.00
Asset Actual Cost \$6,400.00
Percent Replacement 100%
Future Cost \$7,408.13

Clubhouse - Second Floor Components
Placed in Service June 2006
Useful Life 20
Replacement Year 25-26
Remaining Life 3



HVAC Unit 1 - 2031		5 Tons	@ \$1,600.00
Asset ID	1030	Asset Actual Cost	\$8,000.00
		Percent Replacement	100%
Clubhouse - I	Mechanical Systems	Future Cost	\$11,057.12
Placed in Service	June 2020		
Useful Life	12		
Replacement Year	31-32		
Remaining Life	9		
HVAC Unit 2 - 2031		12 Tons	@ \$1,600.00
Asset ID	1029	Asset Actual Cost	\$19,200.00
Asset ID	1027	Percent Replacement	100%
Clubhouse - I	Mechanical Systems	Future Cost	\$26,537.08
Placed in Service	June 2020	Tuture Cost	Ψ20,337.00
Useful Life	12		
Replacement Year	31-32		
Remaining Life	9		
Remaining Life	9		
HVAC Unit 3 - 2033		12 Tons	@ \$1,600.00
Asset ID	1031	Asset Actual Cost	\$19,200.00
		Percent Replacement	100%
Clubhouse - I	Mechanical Systems	Future Cost	\$28,153.18
Placed in Service	June 2022		. , ,
Useful Life	12		
Replacement Year	33-34		
Remaining Life	11		
Č			

Elevator Cab Refurbishment - 2030

Asset ID 1033 Asset Actual Cost

\$8,600.00 Percent Replacement 100% Clubhouse - Elevator **Future Cost** \$11,540.19

1 Lump Sum

@ \$8,600.00

Placed in Service June 2006 Useful Life 25 Replacement Year 30-31 Remaining Life 8



Interior of elevator cab is stainless steel and will require refurbishment or wall panel replacement due to the catering use and delivering of equipment to the ballroom.

Elevator Equipment Modernization - 2040

		2 Stops	@ \$15,600.00
Asset ID	1034	Asset Actual Cost	\$31,200.00
		Percent Replacement	100%
	Clubhouse - Elevator	Future Cost	\$56,265.41
Placed in Service	June 2006		
Useful Life	35		
Replacement Year	40-41		
Remaining Life	18		

One hydraulic elevator serves the upper floor walkway and kitchen. This replacement allowance is for controls and pump equipment. It is assumed the piston can be utilized in this moderization.

Composit Deck & Rails - 2041

Asset ID 1217

740 Square Feet @ \$16.00 **Asset Actual Cost** \$11,840.00 Percent Replacement 100% \$21,992.56 **Future Cost**

Lake Pavilion Placed in Service January 2022 Useful Life 20 Replacement Year 41-42 Remaining Life 19



Exterior Painting - Pavilion - 2022

Asset ID 1193

1,200 Square Feet @ \$2.00 Asset Actual Cost Percent Replacement **Future Cost**

\$2,400.00 100% \$2,400.00

Lake Pavilion Placed in Service June 2006 Useful Life 10 22-23 Replacement Year Remaining Life 0



Metal Roof - Pavilion - 2040

Asset ID 1191

640 Square Feet @ \$16.00 Asset Actual Cost \$10,240.00 Percent Replacement 100% Future Cost \$18,466.59

Placed in Service June 2006
Useful Life 35
Replacement Year 40-41
Remaining Life 18



1218

Wood Bulkhead - 2033

Asset ID

 160 Square Feet
 @ \$68.00

 Asset Actual Cost
 \$10,880.00

 Percent Replacement
 100%

 Future Cost
 \$15,953.47

Placed in Service
Useful Life
Replacement Year
Remaining Life
Lake Pavilion
June 2006
33-34
Remaining Life
Lake Pavilion
June 2006
11



Wood Repair - Pavilion - 2030

Asset ID 1192

740 Square Feet @ \$21.00
Asset Actual Cost \$15,540.00
Percent Replacement 100%
Future Cost \$20,852.86

Placed in Service June 2021
Useful Life 10
Replacement Year 30-31
Remaining Life 8



Asphalt Shingles - 2025

 ngles - 2025
 12 Squares
 @ \$440.00

 Asset ID
 1081
 Asset Actual Cost Percent Replacement
 \$5,280.00

 Percent Replacement Lawn Pavilions
 Future Cost \$6,111.71

Placed in Service
Useful Life
20
Replacement Year
Remaining Life
June 2006
25-26
3



Exterior Painting - 2026

Asset ID 1082 Asset Actual Cost

2,400 Square Feet

@ \$2.00

\$4,800.00

Percent Replacement 100%
Lawn Pavilions Future Cost \$5,722.78
Placed in Service June 2017

Useful Life 10
Replacement Year 26-27
Remaining Life 4



Exterior Painting - 2022

Asset ID 1068

1,800 Square Feet **Asset Actual Cost** \$3,600.00 Percent Replacement **Future Cost** \$3,600.00

Sports Pavilion Placed in Service June 2006 Useful Life 10 Adjustment 4 Replacement Year 22-23 Remaining Life 0



Metal Roof - 2040

Asset ID

1066

870 Square Feet Asset Actual Cost Percent Replacement

Future Cost

@ \$16.00 \$13,920.00 100%

\$25,103.03

@ \$2.00

100%

Sports Pavilion Placed in Service June 2006 Useful Life 35 Replacement Year 40-41 Remaining Life 18



Restroom Refurbishme	nt - 2025	2 Each	@ \$3,500.00
Asset ID	1067	Asset Actual Cost	\$7,000.00
		Percent Replacement	100%
	Sports Pavilion	Future Cost	\$8,102.64
Placed in Service	June 2006		
Useful Life	20		
Replacement Year	25-26		
Remaining Life	3		

Water Cooler - 2022

@ \$1,100.00 2 Each Asset ID 1069 Asset Actual Cost \$2,200.00 Percent Replacement 100% Future Cost **Sports Pavilion** \$2,200.00 Placed in Service June 2006

Useful Life 12 Replacement Year 22-23 Remaining Life 0



Chain Link Back Stops - 2027

Asset ID 1065 Asset Actual Cost Percent Replacement Ball Fields Future Cost \$22,104.23

Placed in Service June 2006
Useful Life 22
Replacement Year 27-28
Remaining Life 5

Chain Link Dugouts & Roof - 2027

Asset ID 1070 Asset Actual Cost \$12,800.00

Percent Replacement 100%

Ball Fields Future Cost \$15,718.57

Placed in Service
Useful Life
22
Replacement Year
Remaining Life
June 2006
22
27-28
5



Chain Link Fencing 4 Ft - 2027

Asset ID 1063 Asset Actual Cost \$14,490.00
Percent Replacement 100%
Ball Fields Future Cost \$17,793.91

Placed in Service
Useful Life
22
Replacement Year
Remaining Life
June 2006
22
27-28

Chain Link Fencing 4 Ft continued...



Chain Link Fencing 6 Ft - 2027

 Fencing 6 Ft - 2027
 320 Linear Feet
 @ \$26.00

 Asset ID
 1064
 Asset Actual Cost Percent Replacement
 \$8,320.00

 Percent Replacement
 100%

 Ball Fields
 Future Cost
 \$10,217.07

	2011 1 10100
Placed in Service	June 2006
Useful Life	22
Replacement Year	27-28
Remaining Life	5

Basketball Court Resurfacing - 2022

Asset ID 1045

1,200 Each @ \$7.00 **Asset Actual Cost** \$8,400.00 Percent Replacement 100% Future Cost \$8,400.00

Basketball Courts Placed in Service June 2013 Useful Life 5 22-23 Replacement Year Remaining Life 0



Basketball Pole & Backboard - 2022

Asset ID 1046

4 EA @ \$1,800.00 Asset Actual Cost \$7,200.00 Percent Replacement **Future Cost** \$7,200.00

100%

Basketball Courts Placed in Service June 2006 Useful Life 15 22-23 Replacement Year Remaining Life 0



Chain Link Fencing - 2024

Asset ID 1048 Asset Actual Cost \$13,888.00
Percent Replacement 100%
Basketball Courts Future Cost \$15,457.34

Placed in Service
Useful Life
22
Adjustment
-3
Replacement Year
Remaining Life
June 2006
22
24-25



Light Poles - 2030

Asset ID 1047 Asset Actual Cost \$12,400.00
Percent Replacement 100%
Basketball Courts Future Cost \$16,639.35

4 EA

@ \$3,100.00

Placed in Service
Useful Life
Replacement Year
Remaining Life
Basketball Courts
June 2006
25
30-31
8

Asphalt Shingles - Maintenance Building - 2025

		14 Squares	@ \$440.00
Asset ID	1043	Asset Actual Cost	\$6,160.00
		Percent Replacement	100%
	Tennis Complex	Future Cost	\$7,130.32
Placed in Service	June 2006		
Useful Life	20		
Replacement Year	25-26		
Remaining Life	3		



Exterior Painting - Maintenance Building - 2022

		1,100 Square Feet	@ \$2.00
Asset ID	1037	Asset Actual Cost	\$2,200.00
		Percent Replacement	100%
	Tennis Complex	Future Cost	\$2,200.00
Placed in Service	June 2006		
Useful Life	10		
Adjustment	7		
Replacement Year	22-23		
Remaining Life	0		

Exterior Painting - Pavilion - 2022

Asset ID 1041



HVAC Unit - Tennis Office - 2022

Asset ID 1036

Placed in Service
Useful Life
Replacement Year
Remaining Life
Tennis Complex
June 2006
2206
22-23

Metal Roof - Pavilion - 2040

Asset ID 1040

2,031 SF @ \$16.00
Asset Actual Cost \$32,496.00
Percent Replacement 100%
Future Cost \$58,602.58

Placed in Service
Useful Life
Replacement Year
Remaining Life
Tennis Complex
June 2006
40-41
40-41

Metal Roof - Pavilion continued...



Refurbishment Allowance - Restrooms - 2025

		1 Lump Sum	@ \$20,000.00
Asset ID	1236	Asset Actual Cost	\$20,000.00
		Percent Replacement	100%
	Tennis Complex	Future Cost	\$23,150.40
Placed in Service	June 2006		
Useful Life	20		
Replacement Year	25-26		
Remaining Life	3		



Water Coolers - 2035

Asset ID 1044 Asset Actual Cost \$4,200.00
Percent Replacement 100%
Tennis Complex Future Cost \$6,533.56

Placed in Service
Useful Life
15
Replacement Year
Remaining Life
June 2021
35-36
13



Wood Pergola - Pavilion - 2027

Asset ID 1219 Asset Actual Cost \$11,200.0

Percent Replacement 100



Aluminium Fence - F	Patio - 2048	168 Linear Feet	@ \$36.00
Asset ID	1162	Asset Actual Cost	\$6,048.00
		Percent Replacement	100%
	Tennis Courts	Future Cost	\$13,816.45
Placed in Service	June 2019		
Useful Life	30		
Replacement Year	48-49		
Remaining Life	26		
Aluminum Bleachers	s - 2033	1 Unit	@ \$2,600.00
Asset ID	1163	Asset Actual Cost	\$2,600.00
		Percent Replacement	100%
	Tennis Courts	Future Cost	\$3,812.41
Placed in Service	June 2006		
Useful Life	28		
Replacement Year	33-34		
Remaining Life	11		
Chain Link Fencing -	- 10 Ft - 2042	1,840 Linear Feet	@ \$31.00
Asset ID	1155	Asset Actual Cost	\$57,040.00
		Percent Replacement	100%
	Tennis Courts	Future Cost	\$109,129.17
Placed in Service	June 2019		
Useful Life	24		
Replacement Year	42-43		
Remaining Life	20		



Chain Link Fencing - 4 Ft - 2029

Asset ID 1157

270 Linear Feet @ \$21.00 Asset Actual Cost \$5,670.00 Percent Replacement 100% Future Cost \$7,386.87

Placed in Service June 2006
Useful Life 24
Replacement Year 29-30
Remaining Life 7



Light Poles - 2030

Asset ID

1154

16 Each Asset Actual Cost Percent Replacement Future Cost @ \$4,400.00
\$70,400.00
100%
\$94,468.56

Placed in Service
Useful Life

Replacement Year
Remaining Life

Tennis Courts
June 2006
30-31
80-31



Shade Pavilions - 2025

Asset ID 1159 Asset Actual Cost \$8,000.00

Percent Replacement 100%

Tennis Courts Future Cost \$9,260.16

Placed in Service
Useful Life

Replacement Year
Remaining Life

June 2006
20
25-26
3



Tennis Court Replenishment Allowance - 2022

8 Each @ \$2,200.00 \$17,600.00 Asset ID 1153 **Asset Actual Cost** Percent Replacement 100% **Tennis Courts Future Cost** \$17,600.00 Placed in Service June 2014 Useful Life Adjustment 1 Replacement Year 22-23 Remaining Life 0



Community Advisors Page 5-61 May 10, 2022

Wind Screens - 2028

Asset ID 1156

8 Courts @ \$1,100.00
Asset Actual Cost \$8,800.00
Percent Replacement 100%
Future Cost \$11,130.71

Placed in Service June 2019
Useful Life 10
Replacement Year 28-29
Remaining Life 6



Wood Bulkheads - 2035

Asset ID 1158

670 Linear Feet @ \$36.00 Asset Actual Cost \$24,120.00 Percent Replacement 100% Future Cost \$37,521.31

Placed in Service
Useful Life
Replacement Year
Remaining Life
Tennis Courts
June 2006
30
35-36
Remaining Life
13

Aluminium Fencing - 2035

 Fencing - 2035
 846 Linear Feet
 @ \$36.00

 Asset ID
 1010
 Asset Actual Cost
 \$30,456.00

 Percent Replacement
 100%

 Swimming Pools - General
 Future Cost
 \$47,377.66

Placed in Service
Useful Life
30
Replacement Year
Remaining Life
31
June 2006
30
35-36
Remaining Life



Asphalt Shingles - Sidewalk Pavilion - 2025

Asset ID 1018 Asset Actual Cost \$1,760.00
Percent Replacement 100%
Swimming Pools - General Future Cost \$2,037.24

Placed in Service
Useful Life

Replacement Year
Remaining Life

June 2006
20
25-26
3



Community Advisors Page 5-63 May 10, 2022

Concrete Pavers - Pool Decks - 2035

Asset ID 1243 Asset Actual Cost \$108,410.40
Percent Replacement 100%
Swimming Pools - General Future Cost \$168,644.31

Placed in Service
Useful Life
30
Replacement Year
Remaining Life
June 2006
35-36
13



Exterior Painting - Pool Slide Tower - 2028

1 Lump Sum @ \$12,000.00
Asset ID 1230 Asset Actual Cost \$12,000.00
Percent Replacement 100%
Swimming Pools - General Future Cost \$15,178.24

Placed in Service
Useful Life
Useful Life
Replacement Year
Remaining Life
June 2019
28-29
6



Community Advisors Page 5-64 May 10, 2022

HVAC Unit - Pool Office - 2022

Asset ID 1015 Asset Actual Cost \$3,200.00

Percent Replacement 100%

Swimming Pools - General Future Cost \$3,200.00

Placed in Service
Useful Life
12
Replacement Year
Remaining Life
June 2006
22-23
0

Lifeguard Chairs - 2022

Asset ID 1170 Asset Actual Cost \$4,200.00

Percent Replacement 100%

Swimming Pools - General Future Cost \$4,200.00

Placed in Service
Useful Life
Useful Life
Replacement Year
Remaining Life
June 2006
22-23
0



Light Poles - 2030

- 2030 6 Each @ \$1,800.00 Asset ID 1008 Asset Actual Cost \$10,800.00 Percent Replacement 100% Swimming Pools - General Future Cost \$14,492.34

Placed in Service
Useful Life
25
Replacement Year
Remaining Life
June 2006
30-31
8

Metal Roof - Pool Slide Building - 2035

Asset ID 1017 Asset Actual Cost \$14,400.00
Percent Replacement 100%
Swimming Pools - General Future Cost \$22,400.78

Placed in Service
Useful Life
30
Replacement Year
Remaining Life
31
June 2006
30
35-36



Pool Furniture Annual Allowance - 2022

Asset ID 1007 Asset Actual Cost \$2,500.00
Percent Replacement 100%
Swimming Pools - General Future Cost \$2,500.00

Placed in Service
Useful Life

Replacement Year
Remaining Life

June 2006

22-23

0



Community Advisors Page 5-66 May 10, 2022

Pool Pumps & Equipment Annual Allowance - 2022

Asset ID 1009 Asset Actual Cost \$8,000.00

Percent Replacement 100%

Swimming Pools - General Future Cost \$8,000.00

Placed in Service
Useful Life
1
Replacement Year
Remaining Life
June 2006
22-23
0



Pool Shade Structures - 2038

Asset ID 1013 Asset Actual Cost \$20,000.00 Percent Replacement 100%

@ \$20,000.00

1 Lump Sum

Percent Replacement 100%
Swimming Pools - General Future Cost \$33,997.14
Placed in Service June 2019

Useful Life 20 Replacement Year 38-39 Remaining Life 16



200 Linear Feet	@ \$64.00
Asset Actual Cost	\$12,800.00
Percent Replacement	100%
Future Cost	\$17,176.10
	Percent Replacement

Pool Slide Refurbishment - 2031

ol Slide Refurbishn	nent - 2031	1 Lump Sum	@ \$16,000.00
Asset ID	1014	Asset Actual Cost	\$16,000.00
		Percent Replacement	100%
Swim	ming Pools - General	Future Cost	\$22,114.23
Placed in Service	April 2022		
Useful Life	10		
Replacement Year	31-32		
Remaining Life	9		

Vinyl Fence - Pool Equipment Yard - 2035

Asset ID	1019	144 Linear Feet Asset Actual Cost	@ \$31.00 \$4,464.00
		Percent Replacement	100%
Swim	ming Pools - General	Future Cost	\$6,944.24
Placed in Service	June 2006		
Useful Life	30		
Replacement Year	35-36		
Remaining Life	13		



Exterior Painting - Pavilion - 2022

Asset ID 1164

3,400 Square Feet @ \$2.00 Asset Actual Cost \$6,800.00 Percent Replacement 100% Future Cost \$6,800.00

Placed in Service June 2006
Useful Life Adjustment 5

Replacement Year 22-23 Remaining Life 0



Metal Roof - Pavilion - 2035

Asset ID 1168

3,214 Square Feet @ \$16.00 Asset Actual Cost \$51,424.00 Percent Replacement 100% Future Cost \$79,995.69

Placed in Service
Useful Life
Replacement Year
Remaining Life
Family Pool Complex
June 2006
30
35-36



Pool Resurfacing - 2028

Asset ID 1166

Placed in Service
Useful Life
Replacement Year
Remaining Life
Family Pool Complex
January 2014
28-29
6



Refurbishment Allowance - Restrooms - 2025

Asset ID 1237

Placed in Service
Useful Life
Replacement Year
Remaining Life
Family Pool Complex
June 2006
20
25-26
3



Wood Pergola - 2030

 Asset ID
 1165
 Asset Actual Cost Percent Replacement
 \$44,800.00

 Family Pool Complex
 Future Cost \$60,116.35

Placed in Service
Useful Life
Adjustment
Seplacement Year
Remaining Life

Tuning Foot Complex
June 2006
20
30-31
80-31



Exterior Painting - Pavilion - 2026

Remaining Life

Asset ID 1210

1 Lump Sum @ \$3,200.00 Asset Actual Cost \$3,200.00 Percent Replacement 100% Future Cost \$3,815.19

Placed in Service
Useful Life
Useful Complex
June 2017
10
Replacement Year
26-27

4

Structure is 24 x 44 with metal roof material

Exterior Painting - Restroom Pavilion - 2022

		1,800 Square Feet	@ \$1.25
Asset ID	1180	Asset Actual Cost	\$2,250.00
		Percent Replacement	100%
	Lap Pool Complex	Future Cost	\$2,250.00

Placed in Service
Useful Life
Useful Life
Replacement Year
Remaining Life
June 2011
22-23
0

Exterior Painting - Restroom Pavilion continued...



Lane Divider Reel - 2030

 Asset ID
 1211
 Asset Actual Cost Percent Replacement
 \$1,940.00

 Lap Pool Complex
 Future Cost \$2,603.25

Placed in Service
Useful Life
Adjustment
Seplacement Year
Remaining Life
June 2006
30-31
80-31



Lane Dividers - 2022

@ \$520.00 8 Lanes Asset ID 1188 **Asset Actual Cost** \$4,160.00 100% Percent Replacement Future Cost Lap Pool Complex \$4,160.00

Placed in Service June 2006 Useful Life 10 Adjustment 6 Replacement Year 22-23 Remaining Life 0



Light Poles - 2035

@ \$3,000.00 Asset ID 1178 Asset Actual Cost \$18,000.00 Percent Replacement 100% Lap Pool Complex **Future Cost** \$28,000.98

6 EA

Placed in Service June 2011 Useful Life 25 Replacement Year 35-36 Remaining Life 13



Community Advisors Page 5-74 May 10, 2022

Metal Roof - Pavilion - 2045

Asset ID 1181

 1,620 Square Feet
 @ \$16.00

 Asset Actual Cost
 \$25,920.00

 Percent Replacement
 100%

 Future Cost
 \$54,188.61

Placed in Service
Useful Life
Useful Life
Replacement Year
Remaining Life
Lap Pool Complex
June 2011
45-46
23



Metal Roof - Restroom Pavilion - 2045

Asset ID 1179

 1,660 Square Feet
 @ \$16.00

 Asset Actual Cost
 \$26,560.00

 Percent Replacement
 100%

 Future Cost
 \$55,526.60

Placed in Service
Useful Life
Useful Life
Remaining Life
Usap Pool Complex
June 2011
45-46
23



Pool Heater Allowance - 2027

Asset ID 1189

Placed in Service
Useful Life
Replacement Year
Remaining Life
Lap Pool Complex
June 2018
27-28
27-28



Pool Lift - 2023

Asset ID 1187

Placed in Service
Useful Life
Adjustment
Replacement Year
Remaining Life
Lap Pool Complex
June 2006
15
23-24
1



Pool Resurfacing - 2022

Asset ID 1175

6,146 Square Feet @ \$14.00 Asset Actual Cost \$86,044.00 Percent Replacement 100% Future Cost \$86,044.00

Placed in Service
Useful Life
Replacement Year
Remaining Life
Lap Pool Complex
June 2011
22-23
22-23



Pool Solar Blanket - 2022

Asset ID 1182

4,200 Square Feet @ \$1.20 Asset Actual Cost \$5,040.00 Percent Replacement 100% Future Cost \$5,040.00

Placed in Service
Useful Life
Replacement Year
Remaining Life
Lap Pool Complex
June 2011
22-23
0



Pool Solar Blanket Reel - 2026

Asset ID 1212

Placed in Service
Useful Life
Replacement Year
Remaining Life
Lap Pool Complex
June 2011
26-27
4



Refurbishment Allowance - Lap Pool Restrooms - 2025

Asset ID 1242 Asset Actual Cost

Asset Actual Cost \$16,000.00
Percent Replacement 100%
Future Cost \$18,520.32

2 Each

@ \$8,000.00

Placed in Service
Useful Life
Replacement Year
Remaining Life
Lap Pool Complex
June 2006
20
25-26
3



Starting Platforms - 2030

Asset ID 1233 Asset Actual Cost \$16,200.00
Percent Replacement 100%

Lap Pool Complex Future Cost \$21,738.50

Placed in Service
Useful Life

Replacement Year
Remaining Life

Lap Fool Complex

June 2006

30-31

Remaining Life



Water Coolers - 2022

Asset ID 1216 Asset Actual Cost \$2,200.00 Percent Replacement 100%

2 Each

Future Cost

@ \$1,100.00

\$2,200.00

Placed in Service
Useful Life

Replacement Year
Remaining Life

Lap Pool Complex
June 2006
2206
22-23



Community Advisors Page 5-79 May 10, 2022

Pool Play Equipment Allowance - 2030

1 Lump Sum @ \$40,000.00 Asset ID 1213 Asset Actual Cost \$40,000.00 Percent Replacement 100% Splash Pool **Future Cost** \$53,675.32 Placed in Service June 2006 Useful Life 25 Replacement Year 30-31 Remaining Life 8



Pool Resurfacing - 2028

Asset ID 1190

Placed in Service January 2014
Useful Life 15
Replacement Year 28-29
Remaining Life 6

 1,870 Square Feet
 @ \$12.00

 Asset Actual Cost
 \$22,440.00

 Percent Replacement
 100%

 Future Cost
 \$28,383.31



Bipod Swings - 2 Bay - 2031

Asset ID 1052

1 Each @ \$3,200.00
Asset Actual Cost \$3,200.00
Percent Replacement 100%
Future Cost \$4,422.85

Playground - Clubhouse
Placed in Service June 2017
Useful Life 15

Useful Life 15
Replacement Year 31-32
Remaining Life 9



Cresent Climber - 2034

Asset ID 1054

Playground - Clubhouse Placed in Service June 2017

Useful Life 18
Replacement Year 34-35
Remaining Life 12



10 Each @ \$1,300.00
t Actual Cost \$13,000.00
Replacement 100%
Future Cost \$17,444.48

D	7 1 1	2027
Picnic 7	ables	8 - 2027

@ \$2,100.00 Asset ID 1059 **Asset Actual Cost** \$8,400.00 Percent Replacement 100% **Future Cost** \$10,315.31

Playground - Clubhouse

Placed in Service June 2006 Useful Life 20 2 Adjustment Replacement Year 27-28 Remaining Life 5



Plastic Play Surface Border - 2036

Asset ID 1057 **Asset Actual Cost** \$10,290.00

Playground - Clubhouse

Placed in Service June 2017 Useful Life 20 Replacement Year 36-37 Remaining Life 14

Percent Replacement 100% **Future Cost** \$16,487.44

@ \$21.00

490 Linear Feet

4 Each

Plastic Play Surface Border continued...



Play Equipment Allowance - 2029

Asset ID 1049

Playground - Clubhouse

Placed in Service October 2017
Useful Life 12
Replacement Year 29-30
Remaining Life 7



Speedy Spinner - 2028

Asset ID 1051

Playground - Clubhouse

Asset Actual Cost Percent Replacement Future Cost

1 Each

@ \$5,000.00
\$5,000.00
100%

\$6,324.27

Placed in Service June 2017 Useful Life 12 Replacement Year 28-29

Remaining Life 6

Community Advisors Page 5-83 May 10, 2022

Speedy Spinner continued...



Spring Riders - 2031

Asset ID 1050

2 Each Asset Actual Cost Percent Replacement **Future Cost**

@ \$1,600.00 \$3,200.00

Playground - Clubhouse

Placed in Service June 2017 Useful Life 15 Replacement Year 31-32 Remaining Life 9

100% \$4,422.85



Wood Park Benches - 2036

Placed in Service

Asset ID 1053

1 Lump Sum Asset Actual Cost Percent Replacement

@ \$1,800.00 \$1,800.00 100%

Playground - Clubhouse

June 2017 20

36-37

Future Cost \$2,884.10

Useful Life Replacement Year Remaining Life 14

> Community Advisors Page 5-84 May 10, 2022

Wood Park Benches continued...



Wood Play Equipment - 2029

Asset ID 1055

Playground - Clubhouse

Placed in Service Useful Life 12
Replacement Year 29-30
Remaining Life 7



Bi-Pod Swing Set - 2022

 ng Set - 2022
 1 Each
 @ \$3,200.00

 Asset ID
 1136
 Asset Actual Cost
 \$3,200.00

 Percent Replacement
 100%

 Playground - Deerview Park
 Future Cost
 \$3,200.00

Placed in Service
Useful Life
15
Replacement Year
Remaining Life
June 2006
22-23
0



Cresent Climber - 2023

Remaining Life

Asset ID 1249 Asset Actual Cost \$2,800.00 Percent Replacement 100%

1 Each

@ \$2,800.00

\$2,968.00

Playground - Deerview Park
Placed in Service
Useful Life
18
Replacement Year
23-24

1



Gazebo Roof - 2035

Asset ID 1131 Asset Actual Cost \$4,800.00
Percent Replacement 100%
Playground - Deerview Park Future Cost \$7,466.93

Placed in Service
Useful Life
30
Replacement Year
Remaining Life
June 2006
35-36
13



Park Benches - 2022

Asset ID 1132 Asset Actual Cost \$1,200.00

Percent Replacement 100%

Playground - Deerview Park Future Cost \$1,200.00

Placed in Service June 2006
Useful Life 16
Replacement Year 22-23
Remaining Life 0



Picnic Tables - 2022

2 Each @ \$1,300.00

Asset ID 1225 Asset Actual Cost \$2,600.00

Percent Replacement 100%

Playground - Deerview Park Future Cost \$2,600.00

Placed in Service
Useful Life
Replacement Year
Remaining Life
June 2006
22-23
Remaining Life
June 2006
0



Plastic Play Surface Border - 2025

Replacement Year

Asset ID 1135

Playground - Deerview Park
Placed in Service June 2006
Useful Life 20

25-26

Remaining Life 3

291 Linear Feet @ \$21.00 Asset Actual Cost \$6,111.00 Percent Replacement 100% Future Cost \$7,073.60



Play Equipment Allowance - 2022

Remaining Life

Asset ID 1130

Playground - Deerview Park
Placed in Service June 2006
Useful Life 15
Replacement Year 22-23



0

Spring Rider - 2022

Asset ID 1247

Playground - Deerview Park
Placed in Service June 2006
Useful Life 15
Replacement Year 22-23
Remaining Life 0



Vinyl Privacy Fence - 2035		200 Linear Feet	@ \$31.00
Asset ID	1224	Asset Actual Cost	\$6,200.00
		Percent Replacement	100%
Playground - De	eerview Park	Future Cost	\$9,644.78
Placed in Service	June 2006		
Useful Life	30		
Replacement Year	35-36		
Remaining Life	13		

Vinyl Ranch Fence - 2030

Asset ID 1129 Asset Actual Cost \$11,088.00
Percent Replacement 100%
Playground - Deerview Park Future Cost \$14,878.80

Placed in Service June 2006
Useful Life 25
Replacement Year 30-31
Remaining Life 8



Bi-Pod Swing Set - 2022

@ \$3,200.00 Asset ID 1141 Asset Actual Cost \$3,200.00 Percent Replacement 100% Future Cost Playground - Hamilton Glen Park \$3,200.00

1 Each

600 SF

Future Cost

@ \$8.00

\$7,466.93

Placed in Service June 2006 Useful Life 15 Replacement Year 22-23 Remaining Life 0



Gazebo Roof - 2035

1137 Asset ID Asset Actual Cost \$4,800.00 Percent Replacement 100%

Playground - Hamilton Glen Park Placed in Service June 2006 Useful Life 30 35-36 Replacement Year Remaining Life 13



Park Bench - 2022

@ \$1,300.00 Asset ID 1142 **Asset Actual Cost** Percent Replacement

Playground - Hamilton Glen Park Placed in Service June 2006 Useful Life 16 Replacement Year 22-23 Remaining Life 0



Picnic Tables - 2022

Asset ID 1143

Playground - Hamilton Glen Park Placed in Service June 2006 Useful Life 16 22-23 Replacement Year Remaining Life 0

2 Each @ \$1,300.00 Asset Actual Cost \$2,600.00 Percent Replacement 100% \$2,600.00 **Future Cost**

1 Each

Future Cost

\$1,300.00

\$1,300.00

100%



Plastic Play Surface Border - 2025

Asset ID 1140

120 Linear Feet @ \$21.00 Asset Actual Cost \$2,520.00 Percent Replacement 100% Future Cost \$2,916.95

Playground - Hamilton Glen Park
Placed in Service June 2006
Useful Life 20
Replacement Year 25-26
Remaining Life 3



Play Equipment Allowance - 2022

Asset ID 1138

Playground - Hamilton Glen Park
Placed in Service June 2006
Useful Life 15
Replacement Year 22-23
Remaining Life 0



Vinyl Privacy Fence - 2035		237 Linear Feet	@ \$31.00
Asset ID	1144	Asset Actual Cost	\$7,347.00
		Percent Replacement	100%
Playground - Hamilton	on Glen Park	Future Cost	\$11,429.07
Placed in Service	June 2006		
Useful Life	30		
Replacement Year	35-36		
Remaining Life	13		

Bi-Pod Swing Set - 2022

Asset ID 1152

1 Each @ \$3,200.00
Asset Actual Cost \$3,200.00
Percent Replacement 100%
Future Cost \$3,200.00

Playgrounds - Whitfield Park
Placed in Service June 2006
Useful Life 15
Replacement Year 22-23
Remaining Life 0



Gazebo Roof - 2035

Asset ID 1147

600 Square Feet @ \$8.00 Asset Actual Cost \$4,800.00 Percent Replacement 100% Future Cost \$7,466.93

Playgrounds - Whitfield Park
Placed in Service June 2006
Useful Life 30
Replacement Year 35-36
Remaining Life 13

Park Bench - 2022

Asset ID 1150

Playgrounds - Whitfield Park
Placed in Service June 2006
Useful Life 16
Replacement Year 22-23
Remaining Life 0

Picnic Tables - 2022

2 Each @ \$1,300.00

Asset ID 1148 Asset Actual Cost \$2,600.00

Percent Replacement 100%

Playgrounds - Whitfield Park Future Cost \$2,600.00

Placed in Service June 2006
Useful Life 16
Replacement Year 22-23
Remaining Life 0



Plastic Play Surface Border - 2025

Asset ID 1151

Playgrounds - Whitfield Park
Placed in Service June 2006
Useful Life 20
Replacement Year 25-26
Remaining Life 3

260 Linear Feet @ \$21.00 Asset Actual Cost \$5,460.00 Percent Replacement 100% Future Cost \$6,320.06



Play Equipment Allowance - 2022

Asset ID 1146

Playgrounds - Whitfield Park
Placed in Service June 2006
Useful Life 15
Replacement Year 22-23
Remaining Life 0



Vinyl Privacy Fence - 2035

Asset ID 1222

426 Linear Feet @ \$31.00 Asset Actual Cost \$13,206.00 Percent Replacement 100% Future Cost \$20,543.39

Playgrounds - Whitfield Park
Placed in Service June 2006
Useful Life 30
Replacement Year 35-36
Remaining Life 13



Vinyl Ranch Fence - 2035

Asset ID 1145 Asset Actual Cost \$11,880.00
Percent Replacement 100%
Playgrounds - Whitfield Park Future Cost \$18,480.65

Placed in Service
Useful Life
30
Replacement Year
Remaining Life
June 2006
35-36
13



@ \$10,000.00	1 Lump Sum		All Terain Vehicle - 2028
\$10,000.00 100%	Asset Actual Cost	1113	Asset ID
\$12,648.53	Percent Replacement Future Cost	op & Equipment	Maintenance Sh
Ψ12,040.33	1 00010 0000	May 2014	Placed in Service
		15	Useful Life
		28-29	Replacement Year
		6	Remaining Life
@ \$2.00	3,300 Square Feet		Exterior Painting - 2022
\$6,600.00	Asset Actual Cost	1080	Asset ID
100%	Percent Replacement	1000	113500 12
\$6,600.00	Future Cost	op & Equipment	Maintenance Sh
		June 2011	Placed in Service
		10	Useful Life
		22-23	Replacement Year
		0	Remaining Life
@ \$5,000.00	3 Each		Golf Cart - 2022
\$15,000.00	Asset Actual Cost	1111	Asset ID
100%	Percent Replacement		
\$15,000.00	Future Cost	op & Equipment	
		June 2006	Placed in Service
		15	Useful Life
		22-23	Replacement Year
		0	Remaining Life
@ \$6,500.00	1 Each	nce - 2025	Jon Boat & Motor Allow
\$6,500.00	Asset Actual Cost	1112	Asset ID
100%	Percent Replacement	****	115500 112
\$7,523.88	Future Cost	op & Equipment	Maintenance Sh
ψ <i>1</i> ,6 2 3.00		June 2006	Placed in Service
		20	Useful Life
		25-26	Replacement Year

Metal Roof - 2040

3,056 Square Feet @ \$16.00

Asset ID 1079 Asset Actual Cost \$48,896.00

Percent Replacement 100%

Maintenance Shop & Equipment Future Cost \$88,177.99

Placed in Service June 2011
Useful Life 30
Replacement Year 40-41
Remaining Life 18



Flooring - Office

Asset ID 1083 Asset Actual Cost

Operating Expense Percent Replacement
Future Cost

100%

100%

Placed in Service June 2006 No Useful Life

Approx 26 SY

Furniture - Second Floor Clubhouse

Asset ID 1119 Asset Actual Cost

Percent Replacement 100%
Operating Expense Future Cost

Placed in Service June 2006
No Useful Life

Interior Painting - Office

Asset ID 1093 Asset Actual Cost

Percent Replacement
Operating Expense Future Cost

Placed in Service June 2006

No Useful Life

Office Equipment & Furniture Allowance

Asset ID 1118 Asset Actual Cost
Percent Replacement 100%

Operating Expense Future Cost

Placed in Service June 2006 No Useful Life

Parking Lot Seal Coat

Asset ID 1127 Asset Actual Cost

Percent Replacement 100%
Operating Expense Future Cost

Placed in Service June 2006
No Useful Life

Steel Trash Cans

Asset ID 1149 Asset Actual Cost \$1,000.00

Percent Replacement 100%
Operating Expense Future Cost \$1,000.00

Placed in Service June 2006
No Useful Life

Wood Mulch - Play Areas

Asset ID 1056 Asset Actual Cost

Percent Replacement 100%
Operating Expense Future Cost
Placed in Service June 2006

Placed in Service No Useful Life

Clock Tower Clock

Asset ID 1245 Asset Actual Cost Percent Replacement

Components Not Included Future Cost

Placed in Service June 2006

No Useful Life

Fabric Shade Awnings - Tennis Curts

Asset ID 1160 Asset Actual Cost

Percent Replacement 100%
Components Not Included Future Cost

100%

Placed in Service June 2006

Useful Life 22

Replacement Year 27-28 Remaining Life 5

> Community Advisors Page 5-103 May 10, 2022

Report Navigation

- **Executive Summary** provides information about projected year end reserve balance, current annual contribution, interest, and inflation rates:
 - Level of Service is the type of reserve study
 - Funding Method is either Component Funding or Pooled Cash
 - Component Funding Contribution is a year one only amount
 - Current Funding Plan currently used by the Association
 - Recommended Funding Plan maintains adequate funding
- **Funding Model Projections** include both your current plan and our recommended plan. The information included in each column is described below:
 - Year begins with your study year generally for a 30-year term
 - Current cost is the current replacement of all components
 - Annual contribution is the amount placed in reserves each year
 - Annual interest earned on your funds
 - Annual expenditures are the projected component replacement cost by year
 - Projected ending balance is the year end reserve fund balance
 - Fully funded reserves are the fully funded balance for that year. Fully Funded formula is Fully Funded Balance= Component cost x Age/Useful Life
 - Percent Funded is a measure of fund strength
- Current Funding Projection is your current funding plan and how it performs
- Recommended Funding Model Projection is the plan we recommend
- Cash Flow is a 30-year statement that provides both income and expense information to quickly find when expenditures occur and the resulting financial status of your reserves
- **Annual Expenditure Detail** provides a year to year list of your projected expenditures This is a good section to review each year when preparing your budgets
- Condition Assessment (if included) is a brief description of major component condition
- **Component Inventory** contains a list of your components, remaining useful life and quantities we determined from our site visit and other means of measurement
- Component Detail Index allows quick access to the detail we have included for each component separated into categories
- Component Detail provides a listing of each component, quantities or allowances and photographs of major ones
- Methodology Terms of Service Company Profile are our Disclosure sections with information about our assumptions, methods of work and our credentials

METHODOLOGY

Reserve Analysis is a process that identifies capital expenses the Association can expect and creates a plan to fund them. This is accomplished by a site visit to visually evaluate components to measure quantities and determine their remaining life. Component Selection Process is based on the Community Associations Institute (CAI) standards for reserve studies and selection of components.

Component must be a commonly owned, have a limited and predictable life, replacement cost must be above a minimum threshold cost. Useful life and replacement cost are obtained from site inspection by experienced inspectors and our database of information, historical information, local Vendors and comparison of similar component cost found at other properties.

The funding plan we develop includes; adequate cash balances, even contributions so all owners pay their fair share over time and moderate contributions with acceptable increases. Percent Funded is defined by industry standards as 70-100% strong, 30-70% fair or adequate and below 30% weak or inadequate. We recommend Full Funding to avoid deferred maintenance or special assessments. Baseline Funding maintains funds above zero resulting is a high risk of special assessments or deferred maintenance and should be avoided. Threshold Funding maintains reserves above a "Threshold" level providing adequate funding with moderate risk.

CREDENTIALS

Community Advisors, LLC provides capital reserve planning, property inspection, and construction oversight for a broad base of clients including High-rise Condominiums, Homeowner Associations, Churches, Private Schools, Time Shares, Active Adult, Municipal Utility Plants, Marinas, Historic Buildings & Museums and commercial investment properties.

Personal Service attention to detail, quick response and valued client relationships.

Range of Experience includes a broad selection of building types, ages and uses from protected historic structures to new communities ready for developer turnover. As commercial general contractors we have experience building many of the types of structure we now provide reserve analysis for, so we understand potential problem areas. As commercial inspectors we have experienced a variety of structural and cosmetic conditions offering solutions for repair. Areas of expertise include MEP systems, energy management, life safety systems, building envelope and roof components, marine structures, street and other site improvements.

Detailed Site Evaluation is Conducted to make sure we know your property and include all your assets in our analysis. With our years of experience with community development and commercial construction projects we understand both horizontal and vertical construction and utilize realistic replacement cost and useful life projections in our analysis. Financial Plan Meets CAI & APRA Standards with information obtained during the site visit we build a custom-made financial plan to ensure adequate funding for future component replacement which equates to maintaining community value.

Reserve Analyst Credentials: Mr. Charles Sheppard is the owner of Community Advisors responsible for field inspection oversight and day to day operations. Mr. Sheppard hold a BS degree from VA Tech and has conducted building evaluations for over 30 years. He is a licensed Florida General Contractor, Home Inspector and earned the professional designations of Certified Construction Inspector (CCI), Professional Reserve Analyst (PRA) and Reserve Specialist (RS).

TERMS OF SERVICE

We have completed an analysis of your capital components that serves as a budgeting tool. This reserve study reflects the information provided by this client and is not for the purposes of performing an audit or estimating construction projects. Our site visit includes visual observation of components that are accessible and safe for our inspectors to evaluate. Roof evaluation is limited to ground observation for sloped roofs and roof top inspection for flat roofs if safe and stable access is available that meets our safety standards.

We are not responsible for any hidden defects or determining the condition of hidden or underground components or systems. Observing environmental conditions, hazardous materials or determine compliance with building codes or other regulations is not included in our scope of work. Our site visit is not a safety inspection and we are not responsible for any hazards that exist. Destructive testing is not conducted. It has been assumed, unless otherwise noted in this report, that all assets have been designed and constructed properly and that each estimated useful life will approximate that of the norm per industry standards and/or manufacturer's specifications.

Projections of component remaining useful life assumes this client will perform necessary preventative maintenance and repair per industry standards. This reserve analysis study and the parameters under which it has been completed are based upon information provided to us in part by the Client and its contractors, assorted vendors, specialist and independent contractors. Reserve fund balances and contribution amounts for use in our analysis is furnished by the client and deemed accurate. Useful life projections are determined by historical records, component condition and our opinion based on evaluating similar components on other projects. These life projections are changed by weather conditions, use, maintenance procedures and other factors out of our control therefore regular updates to this analysis are needed to maintain funding accuracy. Replacement cost is determined by our experience with similar projects, local vendor pricing and client historical records and should not be considered suitable for budgeting repair or replacement projects. Local contractor proposals must be obtained for this work. No liability is assumed as the result of changing market prices or inaccurate estimates or projections of remaining useful life of components.

Component replacement cost and interest rates constantly change. In order to maintain accuracy of your funding plan updates to this analysis should be conducted annually with a site visit every 2-3 years unless conditions warrant annual visits. Community Advisors, LLC shall not be required to participate in any legal action taken by or against our clients for any reason and shall also not be required to give testimony in depositions or in court. In all cases the liability of Community Advisors, LLC and its Principals, Employees, contractors and Vendors shall be limited to the consulting fee agreed upon for the production of this report. Client financial information is considered confidential and is not disclosed to third parties without your approval. We do use your name for our list of valued clients and when submitting proposals for new projects that request references or recent projects. That request may include size of property, number of units or major components. We also use photos from time to time of components as an example for educational and marketing efforts. Community Advisors and the analyst who prepared this study do not have any relationship that can be considered a conflict of interest. From time to time our Clients ask that we manage repair or replacement of components due to our experience in construction management. We do so with the understanding that full disclosure for both parties is completed.

DEFINITIONS

Adjustment to Useful Life: Typical useful life projections are used for each component. The adjustment is used to modify that life projection for earlier or later replacement. It only applies to the current replacement cycle.

Cash Flow Method: A method of determining reserve contributions that are "pooled" to fund replacement cost as needed without restricting funds to any one component.

Component Method: A funding method that fully funds each reserve component then sums those for the annual contribution.

Current Funding Plan: The funding plan currently used at the time of this analysis with updated component inventory and financial assumptions. This allows you to see how the current contribution level funds future component replacement.

Effective Age: Difference of useful and remaining useful life.

Fully Funded Balance: Represents the cost of used component life represented by the formula.

FFB = (Current Cost x Effective Age)/ Useful Life

Interest Contribution: The interest that should be earned on invested reserves.

Percent Funded: Ratio of reserve balance to fully funded balance.

Remaining Life: Number of years a component is projected to continue to function.

Threshold Funding: This plan maintains fund balance above a predetermined threshold dollar or percent funded amount.

Useful Life: The estimated useful life of an asset based upon industry standards, manufacturer specification, visual inspection, location, usage, association standards and prior history. aa